



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10/13/09 Operator High Plains Operations API # 30-0 4321065

Property Name Eagle Springs 9 fed Well # 1 Location: Unit D Sec 9 Twn 19 Rge 4

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

SWS 1189

Temporarily Abandoned Well (Y/N) (N) TA Expires: _____


Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. 0

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. 1017

Pressured annulus up to 540 psi. for 30 mins. Test passed/failed

REMARKS: PACKER SET @ 5043
top of perfor. 5087



Well status in RDBMS is Dry & Abandoned.


John Twyman with well check

By Russell McQuitty
(Operator Representative)

Witness Derrick Vigil
(NMOCD)

Consultant
(Position)

Revised 02-11-02



PRINTED IN U.S.A.