



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-10-09 Operator BP America API #30-0 45-10279
Property Name Riddle CLS Well No. 1 Location: Unit Section 30 Township 31 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 10 Intermediate 2 Casing 108 Bradenhead .5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	TSTM	2	108	TSTM	108
10 min	TSTM	2	108	TSTM	108
15 min	TSTM	2	108	TSTM	108
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD .2 INTERMEDIATE TSTM (.1)

REMARKS: 1" valve on BH and Intermediate, BH blew down quickly in 3 sec., Intermed blew down in 40 sec. then nothing.

By Ray Pedraza
Technician
(Position)

Witness Rachael Wilson

E-mail address