



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-23-09 Operator Conner Phillips API #30-0 45-28549

Property Name San Juan 32.7 Well No. 301 Location: Unit Section 34 Township 32 Range 7

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 625 Intermediate 269 Casing 11 Bradenhead 50

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		11		16
10 min	0		14		-10
15 min	0		15		-11
20 min	0				-11
25 min					-11
30 min					-11

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		/
Surges		
Down to Nothing	/	
Nothing		
Gas		/
Gas & Water		RCVD OCT 23 '09
Water		OIL CONS. DIV.

If bradenhead flowed water, check all of the descriptions that apply below:

DIST. 3

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 3

REMARKS: BH down to light blow in 7 seconds dead in 5 min
Int. Hard Blow first 7 minutes (Chart shows zero) Med blow at 15 minutes
Medium to light blow in 25 min. Casing went to vacuum in 5 min. (Pump started)

By Louis Muehl

Witness Monica Gutierrez

MSD

(Position)

E-mail address