UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Notices and Reports on Wells	RECEIVED		
1.	Type of Well GAS	OCT 23 2009 Bureau of Land Management Farmington Field Office	5. 6.	Lease Number Jicarilla Contract #41 If Indian, All. or Tribe Name Jicarilla Apache
2.	Name of Operator CONOCOPHILLIPS COMPANY	Famington Fleid Cilia	7.	Unit Agreement Name
3.	Address & Phone No. of Operator		8.	Well Name & Number Jicarilla 30 6
	PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	API Well No.
4.	Location of Well, Footage, Sec., T, R, M		10.	30-039-20461 Field and Pool
	Surf: Unit J (NWSE), 2000' FSL & 2200' FEL, Section	29, T25N, R4W, NMPM	11.	West Lindrith Gallup/D County and State Rio Arriba, NM
12.	CHECK APPROPRIATE BOX TO INDICATE NATU Type of Submission Notice of Intent X Subsequent Report Final Abandonment Final Abandonment Type of Action Abandonment Recompletion Plugging Casing Repair Altering Casing	RE OF NOTICE, REPORT, OT Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection		DATA Other - MIT for 300psi
13.	Describe Proposed or Completed Operations			
				RCVD NOV 3'09
				RCVD NOV 3 '09 OIL CONS. DIV.
See	attached sheet for details:			
14.	I hereby certify that the foregoing is true and correct.	nonda Rogers_Title <u>Staff Reg</u> u	<u>latory</u> '	OIL CONS. DIV.

NMOCD

16

ACCEPTED FOR RECORD

OCT 28 2009

PAPMINGTON FIELD OFFICE

Jicarilla 30 6 API 30-039-20461

Note: MIT was conducted as required by OCD to verify integrity of the 300 psi squeezes preformed in 2008.

9/14/09 MIRU AWS 485. 9//15/09 ND WH & NU BOP. PT-OK. TOOH w/tbg. 9/16 & 9/17/09. RIH w/packer & RBP, had trouble with tight spots. Set RPB & 7224'. Unable to set packer. Released RBP. POOH.

9/22/09 RIH w/packer & RBP & set (RBP @ 6415' & packer @ 6383'). 3 attempts to PT to 500# - all leaked off. PT tbg to 1000# leaked off. Replaced bad tubing. Reset packer @ 6383', still not test. Released, POOH w/RBP & packer. Signs of Metal on top of RBP.

9/24/09 Ran Multi Sensor Caliper Log.

9/28/09 RIH & set RBP @ 6415' & packer @ 6385'. PT to 500#/30 min. OK. Moved packer uphole & set @ 4766', 4890', & 5407. PT each to 500# - lost 200# in minutes & then dropped slowly from there. Finished isolating leak in casing. Leak found from 5385' - 5422'. Good casing from 5385' to 287', another leak found from 287' - 256'. Good test again @ 256' - 225'. RIH & released RBP, POOH & LD.

10/5/09 Ran CBL from 6432'- surface. Found no cement behind pipe. Called Wayne Townsend (BLM) & Kelly Roberts (OCD) to report MIT results. Advised agencies that COP wanted to P&A wellbore.

10/6/09 RIH w/235 jts 2-3/8", 4.7# J-55 tbg and set @ 7322'. ND BOP, NU WH. RD & RR.

P&A procedure will be submitted once interval approvals are received.