UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



NOV 1 6 2009

DORAGO OF DAILYD MARYIGENERY	Bure	Man of the	
Sundry Notices and Reports on Wells		Bureau of Land Management	
·	5.	Lease Number SF-078316-E	
I. Type of Well GAS	6.	SF-078310-E If Indian, All. or Tribe Name	
. Name of Operator	7.	Unit Agreement Name	
BURLINGTON 3 RESCURCES OIL & GAS COMPANY LP			
. Address & Phone No. of Operator		Well Name & Number Walker 1M	
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.	
Location of Well, Footage, Sec., T, R, M		30-045-35005	
Surface: Unit P (SESE), 49' FSL & 349' FEL, Section 31, T31N, R9W, NMPM		Field and Pool Blanco MV / Basin DK	
Bottomhole: Unit P (SESE), 710' FSL & 710' FEL, Section 31, T31N, R9W, NMPM	11.	County and State San Juan, NM	
3. Describe Proposed or Completed Operations			
Please See Attached	p		
	FARMING	ED FOR RECORD A A A A A A A A A A A A A A A A A A A	
		RCVD DEG 1'09 OIL CONS. DIV. DIST. 3	
4. I hereby certify that the foregoing is true and correct.			
igned Tafoya Crystal Tafoya Title Regulatory	Technician	Date /1/16/2009	
This space for Federal or State Office use) PPROVED BY Title	D	ate	
CONDITION OF APPROVAL, if any: the 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of e United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction			

Walker 1M API # 30-045-35005 Blanco Mesaverde / Basin Dakota Burlington Resources Oil & Gas Company, LP

11/01/2009 RIH w/ 8 3/4" bit. Tag & DO cmt. Drilled ahead to 3535' - Inter TD reached 11/3/09. Circ. hole. RIH w/ 82jts, 7", 23#, J-55 LT&C set @ 3517' w/ ST @ 2353'. 11/06/09 RU to cmt. 1st Stage - Pre-flush w/ 10bbls GW, 10bbls FW. Pumped scavenger 19sx (57cf-10bbls) Premium lite cmt w/ 3% CACL, .25pps celloflake, 5pps LCM01, .4% FL-52, 8% bentonite, .4% SMS. Lead w/ 88sx (187cf-33bbls) Premium lite cmt w/ 3% CACL, 8% bentonite, .25pps celloflake, .4% FL-52, 5pps LCM-1, .4% SMS. Tail w/ 83sx (115cf-20bbls) Type III cmt w/ 1% CACL, .25pps celloflake, .2% FL-52. Drop plug & displaced w/ 50bbls FW, 86bbls MW. Bump plug. Plug down @ 18:05hrs. Open stage tool & circ. 2bbls cmt to surface. WOC. 2nd Stage - Pre-flush w/ 10bbls GW & 10bbls FW. Pumped scavenger 19sx (69cf-12bbls) Premium lite cmt w/ 3% CALC, .25pps celloflake, 5pps LCM-1, .4% FL-52, 8% bentonite, .4% SMS. Lead w/ 300sx (639cf-114bbls) Premium lite cmt w/ 3% CACL, 8% bentonite, .25pps celloflake, .4% FL-52, 5pps LCM-1, .4% SMS. Drop plug & displaced w/ 93bbls FW. Bump plug & close stage tool. Circ. 30bbls cmt to surface. Plug down @ 23:10hrs on 11/6/09. RD cmt. WOC.

11/07/2009 RIH w/ 6 1/4" bit. Drilled out stage tool @ 2353'. PT 7" csg to 1500#/20min @ 8:00hrs on 11/7/09. Pressure bleed off. Casing leak.

11/08/2009 Agencies contacted regarding failed PT test & requested permission to squeeze. Leak was isolated @ DV tool. BLM (Steve Mason) & OCD granted permission to squeeze & run CBL. Results of CBL are attached. 11/08/2009 Pumped 150sx (209cf-37bbls) Type III cmt w/ 2% CACL2. Displaced w/ 85bbls. WOC. RIH w/ 6 1/4" bit. Drilled cmt to 3468'. Ran CBL. PT csg to 1500#/30min @ 18:45hrs on 11/9/09. Test - OK. Drilled ahead w/ 6 1/4" bit to 7816' (TD) TD reached 11/12/09. Circ. hole & RIH w/ 183jts, 4 1/2", 11.6#, L-80 LT&C set @ 7813', RU to cmt. Preflush w/ 10bbls GW, 2bbls FW. Pumped scavenger 9sx (28cf-5bbls) Premium lite cmt w/ .25pps celloflake, .3% CD-32, 6.25pps LCM-1, 1% FL-52. Tail w/ 310sx (614cf-109bbls) Premium lite cmt w/ .3% CD-32, .25pps celloflake, 1% FL-52, 6.25pps LCM-1. Drop plug & displaced w/ 122bbls FW. Bump plug. Plug down @ 19:05hrs on 11/13/09. RD cmt. WOC. ND BOP. NU WH. RD RR @ 01:15hrs on 11/14/09

PT will be conducted by Completion Rig. Results will appear on next report.

• Report Toc.