submitted in lieu of Form 3160-5

Ì

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT



DEC 03 2009

		Downson Chilly	and Lucital different
	Sundry Notices and Reports on Wells	_ Familio	The Carley
	Type of Well	5.	Lease Number SF-077933
I.	GAS	6.	If Indian, All. or Tribe Name
2.	Name of Operator  BURLINGTON	7.	Unit Agreement Name Huerfano Unit
	RESOURCES OIL & GAS COMPANY LP	<del></del> 8.	Well Name & Number
3.	Address & Phone No. of Operator	0.	Huerfano Unit 244E
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
4.	Location of Well, Footage, Sec., T, R, M	<del></del>	30-045-26265
۲,	inclusion of well, rootinge, occ., r, r, w	10.	Field and Pool
	Surf: Unit A (NENE), 830' FNL & 1160' FEL, Section 19, T26N, R10W, NMPM	11.	Basin Dakota County and State San Juan, NM
12.	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA		
	Type of Submission Type of Action  Notice of Intent X Abandonment Change of Plans		Other -
	Recompletion New Construction X Subsequent Report Plugging Non-Routine Fracture	ring	
ŧ	Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Inject	io <b>n</b>	
	13. Describe Proposed or Completed Operations		
	During the plugging operations we tried to est an injection rate into surf perfs @ 289' & BH. Had no circ.		
	11/18/09 Called Steve Mason (BLM) & Kelly Roberts (OCD), and received verbal appropriate out perfs to cover shoe. Then tie into BH & fill annulus w/ 50 sx cmt & hold	proval to pun 800# on csg	np 42 sx cmt down csg & overnight. RCUD DEC 8 '03
We	ell was P&A'd on 11/18/09. See attached P&A report.		OIL COMS. DIV.
14.	I hereby-certify that the foregoing is true and correct.		DIST. 3
Sig	aned Thomas And Boggs Rhonda Rogers Title Staff	Regulatory T	echnician Date 12/2/0
(Th	nis space for Federal or State Office use)		
CO Title	PROVED BY	~	Date
are U	лико очио ш., чазо, пеннов от напошен значиния от гергозенацова в ю алу matter within из jurisujetion,	ASOEP	TED FOR RECORD
		<b>D</b> <sup>2</sup>	EC 0 4 2009
			apon pipi is orman

NMOCD 16

QC

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 \* fax: 505-325-1211

Burlington Resources Huerfano Unit #244E

November 19, 2009 Page 1 of 1

830' FNL & 1160' FEL, Section 19, T-26-N, R-10-W San Juan Country, NM Lease Number: SF-077933 API#30-045-26265

**Plug and Abandonment Report** 

Notified NMOCD and BLM on 11/16/09

## **Plugging Summary:**

- 11/16/09 MOL and RU. LOTO equipment on location. Open well, no pressure. ND wellhead. NU BOP, test. Tally and TIH with 30 joints 1.5" IJ 2.7# tubing. SI well. SDFD.
- 11/17/09 Open well, no pressure. Tally and TIH with 1.5" IJ 2.7# tubing to 1953'. Load the hole with ½ bbl of water. Establish circulation with an additional 4 bbls of water. Pressure test casing to 580 PSI, held OK for 15 minutes.

  Plug #1 spot 91 sxs Class B cement (107.3 cf) inside casing from 1953' up to 761' to isolate the Pictured Cliffs perforations and cover the Fruitland and Kirtland tops.

  TOH and LD all tubing. Perforate 3 holes at 289'. Load casing with 20 bbls of water. Establish rate 1-1/2 bpm at 1000 PSI with no blow or circulation out the casing. Steve Mason, BLM representative, requested to pump capacity down casing and bradenhead. Plug #2 with 42 sxs Class B cement (49.5 cf) down the 4.5" casing from 289' to surface, shut in casing with 800 PSI; mix and pump 50 sxs Class B cement (59.0 cf) down the bradenhead, shut in bradenhead with 1000 PSI. SDFD.
- 11/18/09 Open well, no pressure. TIH with 1 joint and tag cement in wellhead. ND BOP. Dig out wellhead. Issue Hot Work Permit. Monitor well. Cut off wellhead. Found cement at surface in the 4.5" casing and the annulus. Install P&A marker with 10 sxs Class B cement. RD and MOL.

Jimmy Morris, MVCI representative, was on location. Ron Chavez, BLM representative, was on location.