

30 045 89402

(SUBMIT IN TRIPLICATE)

Land Office **SANTA FE**
Lease No. **SF- 077372**
Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

APPROVED *[Signature]*
ACTING DISTRICT ENGINEER
SEP 24 1953

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SEPTEMBER 20, 19 53

Well No. **2 DANGBY** is located **990** ft. from **N** line and **990** ft. from **E** line of sec. **19**

NE-NE **30N-12W** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
WILDCAT **SAN JUAN** **NEW MEXICO**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5348** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SHOT WITH 110 QTS OF NITRO-GEL FROM 1958 TO 1998.
15' OF GRAVEL ON BOTTOM OF HOLE. SIX FEET OF GRAVEL AND 45
FEET OF CALSEAL USED AS TAMP ON TOP OF SHOT. HOLE CLEANED TO BOTTOM.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **DON TRADERS INC.**
Address **254 NO. LAUREL AVE.**
DES PLAINES, ILL.
By *F.C. Barnes*
F.C. BARNES
Title **GEOLOGIST.**