

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact	Kelsi Gurrutz
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-599-3403
Facility Name	San Juan 27-4 141M	Facility Type	Gas Well
Surface Owner	Forest	Mineral Owner	Federal
		Lease No.	SF-080674
		API #	300-39-30266

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	16	T27N	R04W	855'	North	600'	East	Rio Arriba

Latitude 36.578046° N Longitude 107.248816° W

NATURE OF RELEASE

Type of Release – Produced Water/Natural Gas/Paraffin	Volume of Release – 2.4 BBL /120 MCF/5 Gal	Volume Recovered – 0
Source of Release: Separator	Date and Hour of Occurrence 9/14/09 – Time Unknown	Date and Hour of Discovery 9/15/09 – 1:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	RCVD SEP 28 '09
By Whom?	Date and Hour –	OIL CONS. DIV.
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	DIST. 2
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* On September 14, 2009, sand washed out the bottom of the inlet motor valve creating a 1/8th inch hole in the separator. The well was immediately shut in upon discovery. All fluid remained on location.		
Describe Area Affected and Cleanup Action Taken.* All fluid remained on location. The unit was washed down with Simple Green & oil gator was spread & raked into the soil. The soil will be monitored on future site visits.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Kelsi Gurrutz</i>	OIL CONSERVATION DIVISION	
Printed Name: Kelsi Gurrutz	Approved by District Supervisor: <i>Branch</i>	For: <i>Charlie Perrin</i>
Title: Environmental Consultant	Approval Date: 10-7-09	Expiration Date:
E-mail Address: kelsi.m.gurrutz@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/25/09	Phone: 505-599-3403	

* Attach Additional Sheets If Necessary

Incident # *1 RMD 0928126447*