

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	Moore C #1	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-078147
		API #	30-045-11797

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	T32N	R12W	820'	South	1105'	East	San Juan

Latitude 36.95188° N Longitude 108.07761° W

RCVD JUL 2 '08
OIL CONS. DIV.

NATURE OF RELEASE



DIST. 3

Type of Release – Diesel Fuel	Volume of Release – 10 gal	Volume Recovered – none
Source of Release: Theft	Date and Hour of Occurrence unknown	Date and Hour of Discovery 6/23/08 – 2:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD – Henry Villanueva via phone & email BLM - Kevin Schneider via phone & email	
By Whom? Kristina Kovach	Date and Hour – 6/23/08 – 3:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* A ConocoPhillips employee discovered a spill of approximately 10 gallons of diesel fuel near the Moore C #1 location on the afternoon of 6/23/08 due to a theft. The thieves took diesel fuel from equipment on location and spilled some of the diesel fuel off location.

Describe Area Affected and Cleanup Action Taken.* The diesel fuel was spilled off location. A crew shoveled the affected soil and transported to a landfarm. Envirotech sampled the affected area and determined that all of the diesel had been cleaned up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Kristina L. Kovach	Approved by District Supervisor:  For: Charlie Perrin	
Title: Environmental Associate	Approval Date: 7/2/08	Expiration Date:
E-mail Address: kristina.l.kovach@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/30/08 Phone: 505-326-9866		

* Attach Additional Sheets If Necessary

Incident # 1 RMD 092852633