

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	Allen Com Unit 1A	Facility Type	Gas Well
Surface Owner	State	Mineral Owner	State
		Lease No.	E-5382
		API # 30-045-23572	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	16	T31N	R09W	1560'	North	1140'	West	San Juan

Latitude 36.9010° N Longitude 107.790120° W

NATURE OF RELEASE

Type of Release – crude oil	Volume of Release – 5 BBL Crude oil	Volume Recovered – 4 BBL crude oil
Source of Release: Tank Overflow	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 10/06/08 – 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell via email NM ST Land Office – R. Gallego via e-mail	RCVD OCT 10 '08 CONS. DIV. DIST. 3
By Whom? Kristina Kovach	Date and Hour – 10/8/08 – 4:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips employee discovered a spill of approximately 5 BBL of crude oil at the Allen Com 1A on 10/06/08 due to a below grade tank overflow. The tank overflow was the result of an oil dump that was stuck shut, allowing the tank to overfill. Upon discovery, the employee shut down the pumping unit and had a vacuum truck recover oil from around the pit. Approximately 4 BBL of oil was recovered and put back into the tank.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids remained on location. The spill impacted soil on the ground surface, in and around the pit. The below grade tank will be removed and affected soils will be excavated. To prevent reoccurrence, COPC repaired oil dump and will continue to monitor performance of oil dump.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kristina L Kovach</i>	OIL CONSERVATION DIVISION	
Printed Name: Kristina L. Kovach	Approved by District Supervisor: <i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Title: Environmental Associate	Approval Date: 10/10/08	Expiration Date:
E-mail Address: kristina.l.kovach@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/8/08 Phone: 505-326-9866		

* Attach Additional Sheets If Necessary

Incident # **AKM 0928139679**