District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## **Release Notification and Corrective Action**

OP	ERATOR	☐ Initial Report ☐ Final Report
Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company Kristina Kovach		
Address 3401 E. 30 <sup>th</sup> St., Farmington, NM 87402	Telephone No. 505-326-9866	
Facility Name Vasaly SWD #2	Facility Type Salt Water Dis	posal (SWD) API # 30-045-29936
Surface Owner Private Mineral Owner	Private	Lease No. SF-014538
LOCATION OF RELEASE		
Unit Letter   Section   Township   Range   Feet from the   No	rth/South Line Feet from the	East/West Line County
B 22 T30N R11W 1200'	North 2390'	East San Juan
Latitude36.80178 ° N Longitude107.9770 ° W		
NATURE OF RELEASE		
Type of Release – Produced Water (PW)	Volume of Release – 10 BBL F	
Source of Release: Filter pod C1 had a leak in valve.	Date and Hour of Occurrence       Date and Hour of Discovery         8/16/08 – 12:01 p.m.       8/16/08 – 12:01 p.m.	
Was Immediate Notice Given?  If YES, To Whom?  OCD - Brandon Powell via email  RCVD DCT 6 '08		
BLM - Kevin Schneider via email OIL CONS. DIV.		
Whom? Kristina Kovach Date and Hour – 10/3/08 – 4:00 p.m.		
Was a Watercourse Reached?		
If a Watercourse was Impacted, Describe Fully.*		
The Wallote was implected, Describe Fairy.		
Describe Cause of Problem and Remedial Action Taken.* A ConocoPhillips employee observed a spill of approximately 10 BBL of produced water at the Vasaly SWD #2 on 8/16/08 due to a leaking valve on the C1 filter pod. Upon discovery, the employee shut in the filter pod and locked out the valve.		
Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids were contained within the lined pit, and 8 BBL of produced water were recovered by vacuum truck and unloaded at the Vasaly SWD # 2 facility. The remaining 2 BBL of water evaporated from the pit. To prevent reoccurrence, COPC will install a new valve and monitor for leaks.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
	OIL CONSE	RVATION DIVISION
Signature: Kupting J. Koroch	Approved by District Supervisor:	Batall For: Churk'e
Printed Name: Kristina L. Kovach		rerrin
Title: Environmental Associate	Approval Date: 10/6/08	Expiration Date:
E-mail Address: kristina.l.kovach@conocophillips.com	Conditions of Approval:	Attached
Date: 10/3/08 Phone: 505-326-9866		
* Attach Additional Sheets If Necessary  Incident # nembog 28642724		