

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30 <sup>th</sup> St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	San Juan 32-7 #18M	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-078995
		API #	30-045-34507

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	5	T31N	R7W	678'	South	1712'	East	San Juan

Latitude 36.92313° N Longitude 107.59125° W

### NATURE OF RELEASE

Type of Release – <b>2% KCl Water</b>	Volume of Release – <b>5 BBL</b>	Volume Recovered – <b>none</b>
Source of Release. <b>Tank leak due to corrosion</b>	Date and Hour of Occurrence <b>Unknown</b>	Date and Hour of Discovery <b>8/26/08 – 7:00 p.m.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>OCD - Brandon Powell via email</b> <b>BLM - Kevin Schneider via email</b>	<b>RCVD SEP 25 '08</b>
By Whom? <b>Kristina Kovach</b>	Date and Hour – <b>9/5/08 – 4:00 p.m.</b>	<b>OIL CONS. DIV.</b>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	<b>DIST. 3</b>

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* **A ConocoPhillips Company employee discovered a spill of approximately 5 BBL of 2% KCl water at the San Juan 32-7 #18M on the evening of 8/26/08 due to a leak in a 400 BBL frac tank. The tank developed a crack in the bottom seam at the outer edge of the side wall. The crack was due to corrosion. Upon discovery, the fluids were transferred to another tank on location.**

Describe Area Affected and Cleanup Action Taken.\* **All of the spilled fluids were contained on location, but none were recovered. The affected soils will be raked and monitored to determine if further remediation is necessary. To prevent reoccurrence, COPC will inspect frac tanks on location prior to use.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kristina L Kovach</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Kristina L. Kovach</b>	Approved by District Supervisor: <i>Bob P...</i> For: <i>Charlie Perrin</i>	
Title: <b>Environmental Associate</b>	Approval Date: <b>9/25/08</b>	Expiration Date:
E-mail Address: <b>kristina.l.kovach@conocophillips.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>9/5/08</b> Phone: <b>505-326-9866</b>		

\* Attach Additional Sheets If Necessary

Incident # *NRM 0928247679*