

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	Huerfanito Unit #50E	Facility Type	Gas Well API # 30-045-34705
Surface Owner	State	Mineral Owner	State
		Lease No.	E-3148-21

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	36	T27N	R09W	1525'	North	990'	West	San Juan

Latitude 36.5344100° N Longitude 107.7452600° W

NATURE OF RELEASE

Type of Release - 2% KCl Water	Volume of Release - 50 BBL KCl Water	Volume Recovered - 30 BBL KCl Water
Source of Release: Bottom seam of frac tank split	Date and Hour of Occurrence 9/26/08 - a.m.	Date and Hour of Discovery 9/26/08 - a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell via email BLM - Kevin Schneider via email	RCVD OCT 8 '08 OIL CONS. DIV.
By Whom? Kristina Kovach	Date and Hour - 10/6/08 - 4:00 p.m.	DIST. 2
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* **On the morning of 9/26/08 a COPC employee discovered a spill of approximately 50 BBL of 2% KCl water at the Huerfanito Unit #50E most likely due to corrosion of the bottom seam of the frac tank. Upon discovery, the employee had the leaking frac tank emptied by vacuum truck and the remaining KCl water was transferred to another frac tank.**

Describe Area Affected and Cleanup Action Taken.* **All spilled fluids remained on location with approximately 30 BBL of spilled fluids recovered by vacuum truck and transported by Three Rivers Trucking for disposal at Basin Disposal. The impacted soil will be monitored to determine if further remediation is necessary. To prevent reoccurrence, COPC will continue to perform monthly inspections of tanks to check for corrosion.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kristina L Kovach</i>		OIL CONSERVATION DIVISION	
Printed Name: Kristina L. Kovach		Approved by District Supervisor: <i>Bob Pull</i> For: <i>Charlie Perrin</i>	
Title: Environmental Associate		Approval Date: 10/8/08	Expiration Date:
E-mail Address: kristina.l.kovach@conocophillips.com		Conditions of Approval:	
Date: 10/6/08	Phone: 505-326-9866	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Incident # *NRM 0928239664*