<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance

with Rule 116 on back side of form

Form C-141

Revised October 10, 2003

Release Notification and Corrective Action

OPERATO								Initial	Repo	ort 🛛 Final Report
Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company						Contact	Gwen F	R. Frost		
Address 3401 E. 30 th St., Farmington, NM 87402						Telephone No	o. 505-32 6	3-9549		
Facility Name San Juan 32-9 #12						Facility Type		Gas Well		API # 30-045-10865
Surface Owner Federal Mineral Owner						Federal Lea			se No. SF-078626	
LOCATION OF RELEASE										
Unit Letter M						th/South Line Feet from the Ex			East/West Line County West San Juan	
Latitude 36.90801 ° N Longitude 107. 77269W										
NATURE OF RELEASE										
Type of Release – Produced Water & Condensate Volume of Release – 8 BBL Produced Volume Recovered – 6 BE									ume Recovered - 6 BBL	
										oduced Water & 2 BBL ndensate
Source of Release: Wellhead										e and Hour of Discovery
										9/09 –3:30 p.m.
						If YES, To Whom? OCD - Brandon Powell via e-mail RCVD JUL 30 '09				
☐ Yes ☐ No ☒ Not Required						OCD - Brandon Powell via e-mail KUVU JUL JV VIII BLM – Kevin Schneider via e-mail				
By Whom? Gwen Frost						Date and Hour – 6/02/09 – 4:00 p.m.				
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.				
☐ Yes ☒ No										
If a Watercourse was Impacted, Describe Fully.*										
Describe Cause of Problem and Remedial Action Taken.* On May 29, 2009, a COPC MSO discovered a leak at the 1 inch ball valve										
on pumping tee on wellhead. Approximately 8 BBL produced water & 2 BBL condensate leaked to the ground and										
unrecovered fluids traveled off location approximately 18 feet. Upon discovery, the MSO shut in the pumping unit &										
vacuum truck soaked up remaining standing fluid on ground.										
Describe Area Affected and Cleanup Action Taken.* COPC excavated approximately 24:3 yd3 and disposed of it at Envirotech landfarm. The area of excavation was 18 x 12 x 3.5 feet deep. Envirotech completed conformation sampling before										
backfilling. Backfill soil came from Envirotech. To prevent reoccurrence, COPC will monitor equipment.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to consider a full that the information given above is true and complete to the best of my knowledge and understand that pursuant to consider a full true and complete to the best of my knowledge and understand that pursuant to consider a full true and complete to the best of my knowledge and understand that pursuant to consider a full true and complete to the best of my knowledge and understand that pursuant to consider a full true and complete to the best of my knowledge and understand that pursuant to consider a full true and complete to the best of my knowledge and understand that pursuant to consider a full true and complete to the best of my knowledge and understand that pursuant to consider a full true and complete to the best of my knowledge and understand that pursuant to consider a full true and co										
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability										
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health										
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other										
federal, state, or local laws and/or regulations.						OIL CONSERVATION DIVISION				
Signature: Awan R. Frost										
Signature:	2 00				Approved by District Supervisor: BM SM For: Charlie Persin					
Printed Name	e: G	wen R. Fro								
Title: Environmental Engineer						Approval Date: 7/30/09 Expiration Date:				
E-mail Addre	ess: gwen	dolynne.fro	ost@con	ocophillips.co	<u>m</u>	Conditions of	Approval:			Attached
Date: 7	/28/09		Phone: 5	05-326-9549						
And I Allie I Oliver Year										
Attach Additional Sheets It Necessary Incident # 0926053342										