District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## Release Notification and Corrective Action **OPERATOR** Initial Report Final Report **Burlington Resources, a wholly** Name of Company Contact Gwen R. Frost owned subsidiary of ConocoPhillips Company 3401 E. 30<sup>th</sup> St., Farmington, NM 87402 Address Telephone No. 505-326-9549 Facility Name Sunray J #1A Gas Well API # 30-045-23830 Facility Type **Federal** Federal NM-03195 Surface Owner Mineral Owner Lease No. LOCATION OF RELEASE Unit Letter Section Feet from the North/South Line | Feet from the Township Range East/West Line County 07 **T30N R10W** 1520' South 915' San Juan East 36.82285 ° N Longitude 107. 91834 ° W Latitude NATURE OF RELEASE Type of Release - Produced Water Volume of Release - 15 BBL Volume Recovered - 14.5 BBL Source of Release: Tank overflow Date and Hour of Occurrence Date and Hour of Discovery Unknown 6/05/09 - 10:00 a.m. ROUD JUN 15'09 Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☐ No ☒ Not Required Brandon Powell - via e-mail OIL CONS. DIV. Kevin Schneider - via e-mail By Whom? Gwen Frost Date and Hour $- \frac{6}{09} = 4:30 \text{ p.m.}$ DIST. 3 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.\* Describe Cause of Problem and Remedial Action Taken.\* On June 5, 2009, a COPC MSO discovered that the water pit tank had overflowed & approximately 15 BBL produced water was released. Upon discovery, the MSO shut in the well & notified a vacuum truck to recover standing water in the pit. All spilled fluids remained in the berm. Describe Area Affected and Cleanup Action Taken.\* All of the spilled fluids remained on location in the berm. Approximately 14.5 BBL of produced water was recovered. Soils will be monitored. To prevent reoccurrence, COPC will continue to monitor tank levels. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. **OIL CONSERVATION DIVISION** Signature: Approved by District Supervisor: Printed Name: Gwen R. Frost

Approval Date: /

Conditions of Approval:

\* Attach Additional Sheets If Necessary

6/10/09

**Environmental Engineer** 

E-mail Address: gwendolynne.frost@conocophillips.com

Phone: 505-326-9549

Title:

Date:

Incident # n Rm 0925232721

**Expiration Date:** 

Attached