

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact Gwen R. Frost	
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-326-9549	
Facility Name San Juan 28-6 #204N	Facility Type Gas Well	API # 300-39-30568
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-03583

LOCATION OF RELEASE

Unit Letter I	Section 8	Township T27N	Range R06W	Feet from the 2345'	North/South Line South	Feet from the 915'	East/West Line East	County Rio Arriba
-------------------------	---------------------	-------------------------	----------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude 36.587764° N Longitude 107.484149° W

NATURE OF RELEASE

Type of Release – Drilling Fluids	Volume of Release – 10 BBL	Volume Recovered – 8 BBL
Source of Release: Pit overflow	Date and Hour of Occurrence 1/30/09	Date and Hour of Discovery 1/30/09
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell via email BLM – Kevin Schneider	RCVD FEB 11 '09 OIL CONSERV. DIV. DIST. 2
By Whom? Gwen R. Frost	Date and Hour – 2/9/09 – 4:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **An Aztec Well Service Derrick man turned the yellow dog valve to pit causing pit to fill and flow out of disconnected hopper line. Upon discovery, the rig crew shut the valve to stop the flow. All fluid was contained on location and directed back to ditches and approximately 8 BBL was recovered.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids remained on location. Soils will be monitored. To prevent reoccurrence, COPC will continue to monitor pit levels.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gwen R. Frost</i>	OIL CONSERVATION DIVISION	
Printed Name: Gwen R. Frost	Approved by District Supervisor: <i>Brandon Powell</i>	For: <i>Charlie Perrin</i>
Title: Environmental Engineer	Approval Date: 2/11/09	Expiration Date:
E-mail Address: gwendolynne.frost@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/9/08	Phone: 505-326-9549	

* Attach Additional Sheets If Necessary

nBP0918937118