and the second s					
Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103	
District I	Energy, Minerals and Natural Resources			June 19, 2008	
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	
District II	OII CONSERVA	FION D	WISION		0-045-26232
1301 W. Grand Ave., Artesia, NM 88210 <u>District III</u>				5. Indicate Type of Le	rase FEE
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			6. State Oil & Gas Lea	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV			3	E-2942-2	
1220 S. St. Francis Dr., Santa Fe, NM 87505			. 4.2		
	S AND REPORTS ON WEI			7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Huerfano Unit NP	
PROPOSALS.)					
				8. Well Number	
Oil Well Gas Well X Other				/	194E
2. Name of Operator				9. OGRID Number	
BURLINGTON RESOURCES OIL & GAS COMPANY LP					14538
3. Address of Operator				10. Pool name or Wild	
4. Well Location	Farmington, NM 87499	1.		G	allegos GL
Unit Letter N : 89	0 feet from the S	outh	line and	1750 feet from the	he West line
Section 16	Township 26	N Ran	ge 10W		San Juan
11. EI	evation (Show whether DR,		GR, etc.)		
		564'			
12. Check Ap	propriate Box to Indi	cate Nat	ure of Not	ice, Report or Othe	er Data
NOTICE OF INT	TENTION TO:			SUBSEQUENT R	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL	. WORK	ALTERING CASING
				CE DRILLING OPNS.	P AND A X
	MULTIPLE COMPL		CASING/CE	EMENT JOB	
DOWNHOLE COMMINGLE		Ì			
OTHER:			OTHER:		П
13. Describe proposed or completed	operations. (Clearly state all	pertinent	details, and g	ive pertinent dates, inclu	ding estimated date
of starting any proposed work).		-	•	•	•
or recompletion.					Free Free Free Free Free Free Free Free
•					
			•		
					RCVD JAN 14'10
12/15/09 this well was P&A'd.					
Please see attached report.	Approved for plug	roing of wel	lhore only		OIL ARNS PIV.
· u	Liability under bo	nd is retaine	d pending		01517.3
	Receipt of C-103	(Subsequen	Report of We		
	Plugging) which r under forms.	nay be foun	d @ OCD web	page	
	www.emnrd.state.	us/ocd			
SPUD DATE: 4/22/	1 985 R	IG RELEA	SE DATE:		 1
				L	
I hereby certify that the information above	e is true and complete to the	hest of m	v knowledge	and belief	
SIGNATURE Monda	be us T	ITLE	Staff Re	gulatory Technician	DATE <u>1/13/2010</u>
Type or print name Rhonda	Rogers E-mail :	address:	rrogers@co	onocophillips.com PH	IONE: 505-599-4018
For State Use Only	D man	_			·
\sim \sim \sim \sim \sim) A	Pel	outy Oil	& Gas Inspecto	r. Hann & A mag
APPPROVED BY Taly G. To	T	ITLE	Dis	strict #3	, DATEJAN 1 4 2010
Conditions of Approval (if any):					
/3 # /	.				

.

R

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

Burlington Resources
Huerfano Unit #194E

December 31, 2009 Page 1 of 1

890' FSL & 1750' FWL, Section 16, T-26-N, R-10-W San Juan Country, NM Lease Number: E-2942-2 API #30-045-26232

Plug and Abandonment Report

Notified NMOCD and BLM on 12/14/09

12/14/09 MOL. No equipment on location to LO/TO. RU rig. SDFD.

12/15/09 Open up well; no pressure. Lay relief line to pit. ND wellhead. NU BOP; test. Tally and PU 2.375" EUE 4.7# tubing to 2116'. Load the bradenhead with 1/16 bbl of water. Pressure test bradenhead to 300 PSI. Load casing with 1 bbl of water. Circulate well clean with additional 8 bbls of water. Pressure test casing to 1000 PSI for 10 minutes, held OK for 10 minutes.

Plug #1 with open ended tubing at 2116', spot 29 sxs Class B cement (34.2 cf) inside casing from 2116' up to 1734' to cover the Pictured Cliffs and Fruitland tops. PUH to 1342'. Load the hole with 2 bbls of water.

Plug #2 spot 25 sxs Class B cement (29.5 cf) inside casing from 1342' up to 1013' to cover the Kirtland and Ojo Alamo tops.

PUH to 284'. Load the hole with 2-1/2 bbls of water.

Plug #3 spot 33 sxs Class B cement (38.9 cf) from 284' to surface, circulate good cement out casing valve.

TOH and LD all tubing. ND BOP. Dig out wellhead. Issue Hot Work Permit. Monitor well. Cut off wellhead. Found cement down 5' in the 4.5" casing and at surface in the annulus.

Install P&A marker with 25 sxs Class B cement. SDFD.

12/16/09 RD rig and equipment. Cut off anchors. MOL.

Jimmy Morris, MVCI representative, was on location. Johnny Cole, hCOP representative, visited location.