Form 3160-5 (August 1999) UNITED STATES  DEPARTMENT OF THE INTERIOR  BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000  5. Lease Serial No.		
	SUNDRY	14206032037					
8	Do not use this abandoned wel		6. If Indian, Allottee or Tribe Name EASTERN NAVAJO, SHIP ROCK				
	SUBMIT IN TRII	7. If Unit or CA/Agreement, Name and/or No. NMNM78393X					
1. Type of Well  Oil Well	Gas Well Oth	8. Well Name and No. HGU 292					
2. Name of Operato		9. API Well No. 30-045-22103-00-S1					
3a. Address 10777 WESTHEIMER, SUITE 1100 HOUSTON, TX 77042			3b. Phone No. (include area code) Ph: 505.599.4068 Fx: 505.326.9880		10. Field and Pool, or Exploratory HORSESHOE		
4. Location of Well	(Footage, Sec., T		11. County or Parish, and State				
	R17W NWSE 24 at, 108.58180 W		SAN JUAN COUNTY, NM				
12	. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATE NATURE	OF NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SU	BMISSION	·	TYI	PE OF ACTION			
☐ Notice of In	tent	□ Acidize	Deepen	□ Product	tion (Start/Resume)	☐ Water Shut-Off	
_		☐ Alter Casing	Fracture Treat	□ Reclam	Reclamation Well		
Subsequent	ent Report	☐ Casing Repair	☐ New Construction	n 🗖 Recom	☐ Recomplete ☐ Other		
☐ Final Aband	onment Notice	☐ Change Plans	Plug and Abando	on   Tempor	rarily Abandon		
		Convert to Injection	□ Plug Back	□ Water I	Disposal		
If the proposal is Attach the Bond following compl testing has been	to deepen directions under which the wo etion of the involved	eration (clearly state all pertinerally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices shall be final inspection.)	give subsurface locations and the Bond No. on file with BLI sults in a multiple completion	measured and true v M/BIA. Required su or recompletion in a	ertical depths of all pertir ibsequent reports shall be new interval, a Form 316	nent markers and zones. filed within 30 days 50-4 shall be filed once	
to right until to Load tubing wand establish pulled thread NU BOP, test circulating ho 5-1/2" casing (11/20/03) Optest tubing to cement inside	orqued up. PU or vith 1 bbl and pre- circulation out to s, no pump. ND vit. Attempt to swa le in tubing at 14 scraper to 1345 pen up well, no p 1000#. Pressure e casing above re	ell, no pressure. PU on point polish rod and pull free essure test. Hot oil tubing ubing; 2nd LD polish rod; wellhead. PU on tubing a b fluid, unable to get dow 34'. TOOH w/tubing, x-o 2. Shut in well. SDON. The test casing to 600#. Plue teainer up to 1070' to isolat. Perforate 2 squeeze hot.	, LD subs and rods. RU N : 1st pump 40 bbls hot w 3rd POH and LD guided nd release slips. Install on. RU A-Plus wireline un ver, pup, tubing pump ar 2" DHS cement retainer g #1 with retainer at 1345 ate the Gallup perforation	Mote hot oil truck ater down casing rods, last joint hompanion flange it. Perforate nd SN. Round-tri at 1345'. Pressu 5', spot 32 sxs ns. TOOH with	and JAN	27877 2004 2004 2004 2004	

	:	A.a.	•	
14. I hereby certify that the	te foregoing is true and correct. Electronic Submission #26578 verified For VULCAN MINERALS & ENER Committed to AFMSS for processing by ST	GÝ INC	, sent to the Farmington	
Name (Printed/Typed)	TAMMY WIMSATT	Title	REGULATORY SPECIALIST	
Signature	(Electronic Submission)	Date	01/07/2004	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
Approved By ACCEPTED			TEPHEN MASON PETROLEUM ENGINEER	Date 01/08/2004
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Farmington	

which would entitle the applicant to conduct operations thereon.

Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #26578 that would not fit on the form

## 32. Additional remarks, continued

S ...

bradenhead with 10 bbls water. Plug #2 with 80 sxs cement pumped down the 5-1/2" casing from 177' to surface, circulate good cement returns out bradenhead. Shut in well. SDON. (11/21/03) ND BOP. Dig out and cut off wellhead. Found cement down 8' casing at the surface in the annulus. Had to chip cement out around surface pipe and annulus to cut off. Mix 20 sxs cement to fill casing and install P&A marker. RD. Rig released. R. Maurer, Burlington Resources representative was on location. No Navajo Nation representative was on location. Well was plugged and abandoned 11/21/03.