

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Johnson
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9829
Facility Name	Jicarilla D #11	Facility Type	Gas Well
Surface Owner	Jicarilla Apache Tribe	Mineral Owner	Jicarilla Apache Tribe
		Lease No.	JIC100
			API # 30-039-20566

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	29	T26N	R3W	1190'	North	1190'	East	Rio Arriba

Latitude 36.4569° N Longitude 107.1675° W

NATURE OF RELEASE

Type of Release – Condensate (13 BBL) & produced water (1/2 BBL)	Volume of Release – 13.5 BBL	Volume Recovered – 13.5 BBL
Source of Release: Produced water pit tank overfilled due to rain	Date and Hour of Occurrence 9/7/07	Date and Hour of Discovery 9/7/07 – 1:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell – OCD – via email Dixon Sandoval – Jicarilla Apache Tribe – via email	
By Whom? Monica D. Johnson	Date and Hour – 9/12/07 – 11:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* ConocoPhillips discovered a spill of 13 BBL produced water and ½ BBL condensate at the Jicarilla D #11 on the afternoon of 9/7/07, due to the produced water pit tank overfilling after a heavy rain. The fluids overflowed the tank into a plastic lined bermed area, and all 13.5 BBL were recovered by vacuum truck.

RCVD SEP 13 '07
OIL CONS. DIV.
DIST. 3

Describe Area Affected and Cleanup Action Taken.* All fluids were contained within the bermed area on a plastic liner and all 13.5 BBL were recovered. The pit tank and plastic berm will be steam cleaned. As the soil was not impacted, no further remediation is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Johnson</i>	OIL CONSERVATION DIVISION		
Printed Name: Monica D. Johnson	Approved by District Supervisor: <i>Brandon Powell</i> For: <i>Charles Perrin</i>		
Title: Environmental Specialist	Approval Date: 9-13-07	Expiration Date:	
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 9/12/07 Phone: 505-326-9829			

* Attach Additional Sheets If Necessary

nBP0726050166