District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## **Release Notification and Corrective Action**

	OP.	ERATOR		☐ Initial	Report	
Name of Company Burlington Resource	Contact Monica D. Johnson					
owned subsidiary of ConocoPhillips	(T. 1 )					
Address 3401 E. 30 <sup>th</sup> St., Farmington, NM 87402 Facility Name San Juan 30-6 Unit #472		Telephone No			ADI	# 00 000 04 477
Facility Name San Juan 30-6 Unit #- Surface Owner Federal	Mineral Owner	Facility Type Federa				# 30-039-24477
Surface Owner Federal	Mineral Owner	reuera	<u>II</u>	Leas	e No.	NM SF-080713A
LOCATION OF RELEASE						
Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County						•
A 22 T30N R6W	790'	North	1305'	East	<u>L</u>	Rio Arriba
Latitude36.80319° Longitude107.44573°						
NATURE OF RELEASE						
Type of Release – <b>Produced water</b>			ease - 15 BBL	-		Recovered – 10 BBL
Source of Release: Broken valve					Hour of Discovery – 10:30 a.m.	
Was Immediate Notice Given?		If YES, To Whom?				
☐ Yes ☐ 1	· · · · · · · · · · · · · · · · · · ·	Brandon Powell – OCD – via email				
	Mark Kelly	Mark Kelly – BLM – via email				
By Whom? Monica D. Johnson	Data and Hour 4/19/07 - 5:00 n m					
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.	DĮST. 3					
n a watercourse was impacted, Describe runy.						
into the settling tank cracked, causing the release. All fluids were contained within the bermed area, with 10 BBL recovered by a vacuum truck.						
Describe Area Affected and Cleanup Action Taken.* All fluids were contained within the bermed area, with 10 BBL recovered by a vacuum truck. For remediation of the remaining impacted soils, the soil will be raked.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Signature:	OIL CONSERVATION DIVISION					
Printed Name: Monica D. Johnson	Approved by District Supérvisor: Bundon Juel For Charle					
Title: Environmental Specia	aliet	Approval Date: 7-23-07. Expiration Date:				
				, Expirati	on Date.	
E-mail Address: monica.johnson@conoc  Date: 7/18/07 Phone:		Conditions of .	Approval:		Atta	ched
Date:         7/18/07         Phone:         505-326-9829           Attach Additional Sheets If Necessary         NBf0726033846						
				~ ~ / /	· U ~\/\P	