

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact Monica D. Johnson
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-326-9829
Facility Name San Juan 30-6 Unit #405	Facility Type Gas Well API # 30-039-24589
Surface Owner Private	Mineral Owner Federal Lease No. NM NM-03384

LOCATION OF RELEASE

Unit Letter M	Section 9	Township T30N	Range R6W	Feet from the 790'	North/South Line South	Feet from the 840'	East/West Line West	County Rio Arriba
-------------------------	---------------------	-------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude 36.82205° Longitude 107.47440°

NATURE OF RELEASE

Type of Release – Natural gas	Volume of Release – 384 MCF	Volume Recovered – none
Source of Release: Piping leak at separator inlet	Date and Hour of Occurrence 8/24/07 (from telemetry trend)	Date and Hour of Discovery 8/27/07 – 9:00 a.m.
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required	If YES, To Whom? Brandon Powell – OCD – via email Mark Kelly – BLM – via email	
By Whom? Monica D. Johnson	Date and Hour – 8/27/07 – 12:00 p.m.	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A natural gas release of approximately 384 MCF occurred at the San Juan 30-6 Unit #405, due to a leak in the piping at the inlet to the separator. We suspect CO2 corrosion has compromised the pipe, leading to the line leak. From telemetry, it appears that the release began on 8/24/07 and was discovered and shut in at 9:00 a.m. on 8/27/07. All natural gas was released to the atmosphere.**

Describe Area Affected and Cleanup Action Taken.* **All natural gas was released to the atmosphere. The well is shut in until the leaking pipe is repaired or replaced.**

RCVD AUG 29 '07
OIL CONS. DIV.
DIST. 3

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Johnson	Approved by District Supervisor:  For: Charlie Perrin	
Title: Environmental Specialist	Approval Date: 8-29-07	Expiration Date:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:	Attached ☐
Date: 8/27/07 Phone: 505-326-9829		

* Attach Additional Sheets If Necessary

n BPD726049040