


District I
1625 N French Dr, Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505



Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 25844

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company CONOCO INC.	Contact GARY LEDBETTER
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837
Facility Name JICARILLA E #12A	Facility Type PRODUCTION FACILITY

Surface Owner JICARILLA APACHE TRIBE	Mineral Owner JICARILLA APACHE TRIBE	Lease No. Contract 104
---	---	------------------------

LOCATION OF RELEASE

Unit Letter D	Section 22	Township 26N	Range 4W	Feet from the 30	North/South Line FNL	Feet from the 1150	East/West Line FWL	County RIO ARRIBO
------------------	---------------	-----------------	-------------	---------------------	-------------------------	-----------------------	-----------------------	-------------------

NATURE OF RELEASE

Type of Release PRODUCED OIL&WATER	Volume of Release 7BBLS OIL& 6BBLS OF WATER	Volume Recovered 6 1/2 BBLS OIL/5 1/2 WATER
Source of Release WATER PIT TANK	Date and Hour of Occurrence 2/14/02 3:30PM	Date and Hour of Discovery 2/15/02 2:45 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* OIL DRAIN FROM THE 400 BBLS OIL TANK TO THE 95 BBLS WATER PIT TANK BECAUSE THE DRAIN VALVE WAS OPENED FOR NO KNOWN REASON. THE SEAL WAS BROKEN. AN ACT OF VANDALISM. ALL FREE FLUID WAS PICKED UP BY A VACUUM TRUCK AND PUT BACK IN OIL TANK.

Describe Area Affected and Cleanup Action Taken.* 2 FEET AROUND WATER PIT TANK 1 INCH DEEP. AFFECTED SOIL WILL BE REMOVED AND PROPERLY REMEDATED, NEW SOIL WILL BE ADDED.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: GARY LEDBETTER	Approved by District Supervisor:	
Title: SHEAR SPECIALIST	Approval Date: 2/26/02	Expiration Date:
Date: 2/20/02 Phone: 505-324-5837	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

n DGF02057486/2