District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources of Management of the State of New Mexico

Oil Conservation Division
1220 South St. Francis Dr. APR 2002
Santa Fe, NM 87505

Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective **OPERATOR** Initial Report X | Final Report Name of Company Contact □ R. A. Wirtanen Phillips Petroleum Company Telephone No. □ 505-599-3462 Address 5525 Hwy, 64 Farmington, NM 87401 Facility Type ☐ Gas Well Facility Name San Juan 29-6 Unit #84M Mineral Owner Lease No. □ SF-078278 Surface Owner **Bureau of Land Management Bureau of Land Management** LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line | Feet from the East/West Line County Rie Arriba 29N **6W** 1305' North 926' West D 14 NATURE OF RELEASE Type of Release Volume of Release Volume Recovered

9 bbls **Produced Water** Estimated 10 bbls Source of Release Date and Hour of Occurrence Date and Hour of Discovery 3" valve & bull plug assembly from water tank 1145pm April 24, 2002 reported 0845 4/25/02 Was Immediate Notice Given? If YES, To Whom? X Yes No Not Required NMOCD - Denny Foust via -e-mail. By Whom? Date and Hour 2/5/02 1000 113 4/25/00 Patsy Clugston - Sr. Regulatory Clerk Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Yes X No N/A If a Watercourse was Impacted, Describe Fully.* A watercourse was not reached. Describe Cause of Problem and Remedial Action Taken.* Source - leaking 3" valve and bull plug assembly from a 210 bbl produced water tank, which "un-threaded" as a unit when the Key driver was only trying to remove the bull plug to pull a load. Describe Area Affected and Cleanup Action Taken.* Spilled produced water did not leave location. The 9 bbls of water recovered was taken to the 29-6 #301 SWD for disposal. No further action will be taken to remediate. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by □ District Supervisor: Printed Name: Patsy Clugston

Phone: 505-599-3454

Title: Sr. Regulatory Clerk

4/25/02

Attached

^{*} Attach Additional Sheets If Necessary