


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

30 039 27041

OPERATOR

☐ Initial Report

☒ Final Report

Name of Company Williams Energy	Contact Roxanne Roberts	
Address One Williams Center MD 26-5	Telephone No. (918) 573-0195	
Facility Name Rosa 381	Facility Type: coal bed methane well	
Surface Owner USFS/BLM	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section 11	Township 31N	Range 6 W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
-------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	-------------------

NATURE OF RELEASE

Type of Release diesel fuel	Volume of Release: 18 barrels	Volume Recovered: 15 barrels
Source of Release: fuel tank valve	Date and Hour of Occurrence 11/1/2002 @ 2:00 A.M.	Date and Hour of Discovery 11/1/2002 @ 2:00 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust	
By Whom? Roxanne Roberts	Date and Hour: 11/1/2002 @ 12:20 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Aztec Well Service was on site to refill the fuel tank. After filling the tank the hose fell to the ground and knocked open a valve. The open valve allowed the diesel to spill to the ground. Aztec recovered 15 barrels free liquid and plans have been made to land farm the contaminated soils with nitrogen fertilizer.		
Describe Area Affected and Cleanup Action Taken.* The area affected by the spill include the area around the well site and the path where fuel traveled approximately 30 feet off site.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>Roxanne Roberts</u>	OIL CONSERVATION DIVISION	
Printed Name: Roxanne Roberts	Approved by <input type="checkbox"/> District Supervisor: <u>Denny Foust</u> <u>for Frank Chavez</u>	
Title: <u>EHS Coordinator</u>	Approval Date: <u>11/12/02</u>	Expiration Date: _____
Date: <u>11/1/02</u> Phone: (918) 573-0195	Conditions of Approval: <u>Land farm</u>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

contaminated material on ~~site~~ well pad
as agreed by Roxanne Roberts,
N DGT 0230553336