

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-039-29921

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company Williams Production	Contact Michael K. Lane	RCUD MAY29'07
Address PO Box 640	Telephone No. 505-634-4219	OIL CONG. DIV.
Facility Name Rosa 163B	Facility Type Well Site	DIST. 3
Surface Owner BLM	Mineral Owner BLM	Lease No.

LOCATION OF RELEASE

Unit Letter B	Section 24	Township 31 N	Range 6W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
-------------------------	----------------------	-------------------------	--------------------	---------------	------------------	---------------	----------------	-----------------------------

Latitude Longitude

NATURE OF RELEASE

Type of Release Drilling Mud and Produced Water	Volume of Release ~60 bbl	Volume Recovered ~29 bbl
Source of Release Blow Pit	Date and Hour of Occurrence <5/24/07 10:00 AM	Date and Hour of Discovery 5/24/07 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - NMOCD	
By Whom? Myke Lane, WPX	Date and Hour 5/24/07 16:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.		
Describe Cause of Problem and Remedial Action Taken. During well completion, 2" air bypass line misdirected blowing mud from pit over blow pit containment.		
Describe Area Affected and Cleanup Action Taken. Following discovery, bypass line repositioned, oversprayed mud recovered with vacuum truck and impacted soil scrapped up. Soil samples of impact area and background collected.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael K. Lane	Approved by District Supervisor:  For: Charlie Perrin	
Title: SJB EH&S Specialist	Approval Date: 5-29-07	Expiration Date:
E-mail Address: myke.lane@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/25/07 Phone: (505) 330-3198		

* Attach Additional Sheets If Necessary

nBP0719355074