


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



Release Notification and Corrective Action

3004509278

OPERATOR

x Initial Report Final Report

Name of Company: Devon Energy Production Co. L.P.	Contact <input type="checkbox"/> Mr. Steve Zink, Production Foreman
Address: 3300 N. Butler, Suite 211, Farmington, NM 87401	Telephone No. <input type="checkbox"/> (505) 324-0033
Facility Name: NEBU 103	Facility Type: Well site

Surface Owner: Bureau of Reclamation	Mineral Owner: Bureau of Land Management	Lease No. <input type="checkbox"/> SF 078615
--------------------------------------	--	--

LOCATION OF RELEASE

Unit Letter N	Section 24	Township 30N	Range 08W	Feet from the	North/South Line	Feet from the	East/West Line	County San Juan
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------------

NATURE OF RELEASE

Type of Release: 2% KCL Water	Volume of Release ~8 bbls	Volume Recovered <input type="checkbox"/> 0 bbls
Source of Release: Reserve pit	Date and Hour of Occurrence 08/15/02 12:00 PM	Date and Hour of Discovery <input type="checkbox"/> 8/15/02 12:00 PM
Was Immediate Notice Given? Not Required X Yes (within 24 hrs) <input type="checkbox"/> No <input type="checkbox"/>	If YES, To Whom? Denny Foust, New Mexico Oil Conserv. (505) 334-6718 x15.	
By Whom? <input type="checkbox"/> Kenny Rhoades Devon Energy	Date and Hour <input type="checkbox"/> 8/15/02 1:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Spill was confined to a dry drainage approximately 1200' from location and 1 mile from Navajo Dam Reservoir

Describe Cause of Problem and Remedial Action Taken.\*

Crew was cleaning out well into small reserve pit that was lined and fenced. Well unloaded and overfilled pit resulting in ~8 bbls 2% KCL water spilling over onto ground. Approximately 3 bbls ended up in dry sand wash below location running ~ 1200' from location in a path ~ 2' wide.

Describe Area Affected and Cleanup Action Taken.\*

An area approximately 1200 ft<sup>2</sup> downgradient of the well site received fluid. A crew was called to location and built a land farm on location that will be maintained by Devon Energy representatives. The crew then cleaned up all contaminated soil and put in land farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Steve Zink	Approved by <input type="checkbox"/> District Supervisor: for Frank Chavez	
Title: Production Foreman	Approval Date: 8/29/02	Expiration Date:
Date: August 16, 2002	Phone: (505) 324-0033	Conditions of Approval: Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

NDGFO222833656