

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact	Beverly J. Cox
Address	3401 E. 30 <sup>th</sup> St., Farmington, NM 87402	Telephone No.	505-324-6194
Facility Name	San Juan 32-9 Unit #20	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF 078438

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	18	31N	9W	990'	North	990'	East	San Juan



Latitude 36.902630° Longitude -107.815060°

RCVD JAN 4 '08  
OIL CONS. DIV.  
DIST. 2

### NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 15 bbls	Volume Recovered – 0
Source of Release: produced water tank	Date and Hour of Occurrence 12/28/07 1pm	Date and Hour of Discovery 12/28/07 1pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell – OCD – via phone on 12/31/07 Mark Kelly – BLM – via email	
By Whom? Beverly Cox	Date and Hour – 12/31/07 – 10am.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* No		
Describe Cause of Problem and Remedial Action Taken.* Produced water leak from tank. Tank was emptied and bottom was inspected to find a hole in the tank. The tank has been isolated from service and will be replaced.		
Describe Area Affected and Cleanup Action Taken.* The soil will be monitored for any potential impacts to the vegetation and cleaned and raked accordingly.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

### OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor:  For: Charlie Perrin	
Printed Name: Beverly J. Cox	Approval Date: 1-4-08	Expiration Date:
Title: Sr. Environmental Technologist	Conditions of Approval:	
E-mail Address: <a href="mailto:beverly.j.cox@conocophillips.com">beverly.j.cox@conocophillips.com</a>	Attached <input type="checkbox"/>	
Date: 1/2/08 Phone: 505-324-6194		

\* Attach Additional Sheets If Necessary

n370800937726