District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copics to appropriate District Office in accordance

Form C-141 Revised June 10, 2003

District Office in accordance with Rule 116 on back side of form

| Release Notification and Corrective Action  OPERATOR  Initial Report  Final Report   |   |
|--|---|
| Name of Company Burlington Resources   | Contact Ed Hasely   |
| Address P.O. Box 4289 Farmington NM 87499  | Telephone No. (505) 327-9700  |
| Facility Name UTE 6  | Facility Type Gas Well API# 30-045-11395                              |
| Surface Owner Indian Mineral Owner Indian Lease No. I-22-IND-2772  |   |
| LOCATION OF RELEASE  |   |
| Unit Letter Section Township Range Feet from the North/Sc<br>M 17 032N 014W 1100 Sc  | outh Line Feet from the East/West Line County outh 1000 West San Juan |
| NATURE OF RELEASE  |   |
| Type of Release Produced Oil and Produced Water  | Volume of Release 55 BBLS. Volume Recovered 0 BBLS.                   |
| Source of Release Production Storage Tank  | Date and Hour of Occurence Date and Hour of Discovery                 |
| Was Immediate Notice Given? ✓ Yes ☐ No ☐ Not Required  | 2/28/2007 2/28/2007  If YES, To Whom? Henry N                         |
| By Whom? Ed Hasely   | Date and Hour 3/1/2007  |
| Was a Watercourse Reached? ☐ Yes ✓ No  | If YES, Volume Impacting the Watercourse.                             |
| If a Watercourse was Impacted, Describe Fully.*  | RCVD MAR29'07   |
|  | OIL CONS. DIV.  |
|  | DIST. 3   |
| Describe Cause of Problem and Remedial Action Taken *  | D/ 2.72 1   |
| A hole in the production tank allowed 20 bbls of produced oil and 35 bbls of produced water to leak out into the bermed area.  |   |
| Describe Area Affected and Cleanup Action Taken *  |   |
| All released fluids were contained inside the bernned area. No fluids were recovered. Impacted soils were planned to be excavated and hauled to a commercial landfarm with the excavation to be backfilled with clean soils. Samples of the bottom and a composite of the walls were planned to be taken which will be included in the final report.   |   |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. |   |
| Signature: Magain C  | OIL CONSERVATION DIVISION   |
| Printed Name for Ed Hasely Approved by District Supervisor: Branchon Found For: Charlie Pernica  |   |
| Title: Environmental Representative Approval I   |   |
| E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com Conditions  | s of Approval: Attached   |
| Date: Phone: (505) 326-9841or 9537   |   |

<sup>\*</sup> Attach Additional Sheets If Necessary