## Wildensign. Dist. 3

<u>District 1</u>
1625 N. French Dr., Hobbs, NM 88240
<u>District II</u>
1301 W. Grand Avenue, Artesia, NM 88210
<u>District III</u>

1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised June 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action														
API 30-045-27004						,	CRATOR		Initia	l Report		Final Report		
Name of Company Burlington Resources						Contact		Hasely						
Address P.O. Box 4289 Farmington NM 87499						Telephone No. (505) 326-9700								
Facility Name Middle Mesa SWD #1						Facility Type Salt Water Disposal Well								
Surface Owner BLM Mineral Owner						r	BLM Lease No. NM-2996						2996	
					LOCAT	ΓΙΟΝ	OF RELI	EASE						
Unit Letter	Section	Township	- 1 - 1				1 1 7							
L	25	32N	7 W	1555	Sou	uth	1210		West		San Juan			
NATURE OF RELEASE														
Type of Release Produced Water							Volume of Release 15 BBLS. Volume Recovered 14 BBLS							
Source of Release Primary Filter Pod							Date and Hour of Occurence 2/8/2007				Date and Hour of Discovery 2/8/2007			
Was Immediate Notice Given? ☐ Yes ☐ No ☑ Not Required							If YES, To Whom?							
By Whom?						Date and Hour								
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.								
If a Watercours	e was Impa	eted, Descri	be Fully.	k		<u> </u>								
None. All con	nameu wi	inii iaciii	y bounda	11 y										
Describe Cause											_			
A filter pod drain valve was not closed all the way after changing filters. Water drained throught the partially open valve and overflowed the open top pit tank.														
Describe Area	Affected and	d Cleanup A	Action Tal	ken.*							-			
Describe Area Affected and Cleanup Action Taken.*  All fluids were contained inside the cribbed area around the pit tank. A vacuum truck was used to recover all the free standing liquids.														
regulations all of health or the er operations have	operators and any ironment. It is a failed to act to a failed	re required The accordequately in h, NMOCD	to report eptance o evestigate acceptan	ove is true and co and/or file certain of a C-141 report and remediate co acc of a C-141 report	in release no t by the NM ontamination	otification IOCD ma that pose	s and perform arked as "Fina e a threat to	n corrective I Report" c ground war	e actions fo loes not re ter, surface	or releases elieve the c water, hu	which ma operator of iman healt	ay enda f liabıli th or th	anger public ity should their he	
Signature: Sl Hanh							OIL CONSERVATION DIVISION							
Printed Name   = l Hasel, Appro						by District Supervisor Paramon Ponell For: Charlie Perin								
Title. Environ	nental Repr	esentative			Approval Da	ate	4-07			piration D	ate <sup>,</sup>			
E-mail Address	· lhasely@t	or-inc. com	or gwurtz	@br-inc com	Conditions						Attached			
Date: 2/9	707	Phone: (505	) 326-984	11or 9537	1								]	

<sup>\*</sup> Attach Additional Sheets If Necessary