


District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised March 17, 1999

Submit 3 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

30 045 27336

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>BP America Production Company</b>	Contact <b>Brittany Benko</b>	
Address <b>200 Energy Court Farmington, NM 87401</b>	Telephone No. <b>(505) 326-9235</b>	
Facility Name <b>Dawson GC #1</b>	Facility Type <b>Wellsite</b>	
Surface Owner <b>BLM</b>	Mineral Owner <b>BLM</b>	Lease No. <b>NMNM013685</b>

**LOCATION OF RELEASE**

Unit Letter <b>N</b>	Section <b>31</b>	Township <b>31N</b>	Range <b>8W</b>	Feet from the <b>1210</b>	North/South Line <b>South Line</b>	Feet from the <b>660</b>	East/West Line <b>West Line</b>	County <b>San Juan County</b>
-------------------------	----------------------	------------------------	--------------------	------------------------------	---------------------------------------	-----------------------------	------------------------------------	----------------------------------

**NATURE OF RELEASE**

Type of Release <b>Produced Water</b>	Volume of Release <b>17 bbls</b>	Volume Recovered <b>15 bbls</b>
Source of Release <b>Produced Water Pit</b>	Date and Hour of Occurrence <b>02/06/2002 early morning</b>	Date and Hour of Discovery <b>02/06/2002 9:00 am</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <b>The dump line to the production tank froze causing the separator and compressor suction scrubber to fill with water. The compressor scrubber then continued to dump to the pit, which filled and overran 17 barrels of produced water. The line freeze was most likely due to the compressor being down during the previous day. A water-hauling truck was called out immediately and was able to recover 15 barrels.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>The spill did not breach the berm. The impacted soil is being landfarmed on site.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Brittany D Benko</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Brittany D Benko</i>		Approved by District Supervisor: <i>Verny Feunt for Frank Chavez</i>	
Title: <i>Field Environmental Coordinator</i>		Approval Date: <i>02/20/02</i>	Expiration Date:
Date: <i>02/11/02</i>	Phone: <i>326-9235</i>	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

*NDG-F0205135254*