<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OP	ERATOR		Initial Rep	oort 🛛 Final Report
Name of Company ConocoPhillips Company	Contact	act Monica D. Johnson		
Address 3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-982	505-326-9829	
Facility Name Blanco #201	Facility Type	Gas Well	(API # 30-045-27446
Surface Owner Federal Mineral Owner	Federal		Lease No	o. NM-012641
LOCATION OF RELEASE				
Unit Letter Section Township Range Feet from the Nort L 35 T31N R8W 1560'	h/South Line Fe South		West Line Nest	County San Juan
Latitude36.85176° N Longitude107.65109° W				
NATURE OF RELEASE				
Type of Release – Produced water (Fruitland Coal)	Volume of Releas			lume Recovered – 1 BBL
Source of Release: Line break due to freezing	Date and Hour of 1/23/08	Occurrence		te and Hour of Discovery 23/08 – 5:30 p.m.
Was Immediate Notice Given?				
Yes No Not Required	Brandon Powell – OCD – via phone & email Herman Lujan – BLM – via email			
By Whom? Monica D. Johnson		1/25/08 - 4:00 p		CUN TAN 29 YAR
Was a Watercourse Reached?		Impacting the Water		MCCOMS.DIV.
☐ Yes ☒ No		<u></u>		nero
If a Watercourse was Impacted, Describe Fully.*				which The E. St. Ten
Upon discovery, the valve from the tank to the transfer pump was closed. All of the spilled fluids were contained within the berm, a vacuum truck was dispatched, and 1 BBL was recovered from the berm (the rest of the standing fluids were frozen). Describe Area Affected and Cleanup Action Taken.* All of the spilled fluids were contained within the berm, and 1 BBL was recovered from the berm by vacuum truck. Once the frozen spilled fluids melt, fertilizer will be raked in to the impacted soil to promote rehabilitation, and will be evaluated for any further remediation (excavation) if needed.				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Signatura III	OIL CONSERVATION DIVISION			
Signature: MMCCe D Jambon	/ n. chartie			
Printed Name: Monica D. Johnson	Approved by District Supervisor: Brand Fell For: Charlie Perrin			
Title: Senior Environmental Scientist	Approval Date:	-29-08	Expiration D	Pate:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Ap	proval:		Attached
Date: 1/25/08 Phone: 505-326-9829			,	
trach Additional Sheets If Necessary n BPO 804433944				