


District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form



Release Notification and Corrective Action

30 045 27630

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company CONOCOPHILLIPS	Contact GARY LEDBETTER
Address 3315 BLOOMFIELD HWY ; FARMINGTON, NM 87401	Telephone No. 505-324-5837
Facility Name FC Federal #2	Facility Type PRODUCTION FACILITY

Surface Owner BLM	Mineral Owner BLM	Lease No. SF 078119
----------------------	----------------------	---------------------

LOCATION OF RELEASE

Unit Letter L	Section 12	Township 32N	Range 11W	Feet from the 1500	North/South Line FSL	Feet from the 1220	East/West Line FWL	County SAN JUAN
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	-----------------

NATURE OF RELEASE

Type of Release 50/50 MIX OF ETHYLENE GLYCOL (ANTIFREEZE) & WATER	Volume of Release 60 GALS	Volume Recovered 35 GALS
Source of Release HEAT TRACE HOSE	Date and Hour of Occurrence 10/7/02 UNKNOWN	Date and Hour of Discovery 10/7/02 10:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A HEAT TRACE HOSE ATTACHED TO THE COMPRESSOR SCRUBBER DUMP LINE BECAME FATIGUE WITH AGE AND BUSTED. 35 GALS OF FREE LIQUID WAS PICKED UP AND WILL BE RECYLCED THROUGH SAFETY KLEAN.

Describe Area Affected and Cleanup Action Taken.  
THE AREA AFFECTED WAS A PREPARED SURFACE CLEAR OF VEGETATION. THE CONTAMINATED SOIL WILL BE REMOVED AND TAKEN TO ENVIROTECH LANDFARM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: GARY LEDBETTER	Approved by District Supervisor:	
Title: SHEAR SPECIALIST	Approval Date: 10/15/02	Expiration Date:
Date: 10/8/02 Phone: 505-324-5837	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

NMPK022814877