<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources 15 16 17 18 19

Oil Conservation Division 1220 South St. Francis DR Santa Fe, NM 87505

Form C-141 Revised March 17, 199

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of forn

Release Notification and Corrective Action &							
3004527935		OF	PERATO	R Vic	X□ Initial R	eport X Final Repo	
Name of Company		(Contact R. A. Wirtanen' Z W. Wirtanen'				
Phillips Petroleum Company			T 1 1 N C 505 500 24/2				
Address 5525 Hwy. 64 Farmington, NM 87401			Telephone No.□505-599-3462				
			Facility Type Water Disposal Well				
San Juan 32-8 #301 SWD							
Surface Owner Mineral Owner			Lease No.: E-5113-21				
State State							
LOCATION OF RELEASE							
Unit Letter Section Township Range Fe	et from the 1643'		South Line	Feet from the Ea	st/West Line West	County□ San Juan	
NATURE OF RELEASE							
Type of Release Produced Water			500 bbls	Volume of Release Volume Recovered Approx. 450 bbl			
Source of Release				our of Occurrence	Date and Hour of Discovery 1/12/02		
Broken expansion jt on sucker header to transfer pump				early morning	@ 0700 hrs by PPCo Operator		
Was Immediate Notice Given?			If YES, To Whom?				
X Yes No Not Required			NMOCD - Denny Foust via -e-mail.				
By Whom?			Date and Hour □ 1/14/02 @ 1030 hrs				
Patsy Clugston – Sr. Regulatory Clerk				V			
Was a Watercourse Reached?			If YES, Volume Impacting the Watercourse.				
☐ Yes X No			N/A				
If a Watercourse was Impacted, Describe Fully.*			1	·			
A watercourse was not reached.							
Describe Cause of Problem and Remedial Action Taken.*							
The cause of this spill was a broken expansion joint on the sucker header to the transfer pump. The entire location is bermed and nothing left the							
location. Key Energy sucked up the water and hauled the dirty water to Basin Disposal. We are figuring that approx. 90% of the water was							
collected.							
Describe Area Affected and Cleanup Action Taken.*							
Spilled produced water did not leave location, and once the water was sucked up was hauled off, no further action was taken to remediate.							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and							
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger							
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health							
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other							
federal, state, or local laws and/or regulations.	cc or a e-141 re	-port c	ioes not renev	e the operator of resp	onsidinty for co	impliance with any other	
Signature: Fatsy Cluss			OIL CONSERVATION DIVISION				
				Approved by District Supervisor:			
Printed Name: Patsy Clugston				ים ואועם visitici Supervisor	for Fil	ank Chavez	
Title: Sr. Regulatory Clerk Approval Date: 0[/7/02 Expiration Date:						Date:	
Date: 1/14/02 Phone: 505-599-34	154		Conditions o			Attached	

* Attach Additional Sheets If Necessary

1DGF0201757073