

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

ADP 30-045-29095

OPERATOR

Initial Report Final Report

Name of Company XTO Energy Inc.	Contact Lisa Winn	RCVD DEC27'06 OIL CON. DIV.
Address 2700 Farmington Ave, Bldg K, Ste. 1, Farmington, NM 87401	Telephone No. (505) 566-7942	
Facility Name Gallegos #4E	Facility Type Gas Well (Dakota)	

Surface Owner Fed	Mineral Owner Fed	Lease No. SWI4277
--------------------------	--------------------------	--------------------------

LOCATION OF RELEASE

DIST. 3

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	33	26N	11W	1190	South	1800	West	San Juan

Latitude 36.4405 Longitude 108.01180

NATURE OF RELEASE



Type of Release Produced Oil	Volume of Release Approx 10 bbl	Volume Recovered Approx 10 bbl
Source of Release Drain valve on production pit	Date and Hour of Occurrence 12/07/06, time unknown	Date and Hour of Discovery 12/07/06 at 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully *
N/A

Describe Cause of Problem and Remedial Action Taken * During transfer from a frac tank to a production tank a drain valve was left open.
Produced oil spilled into the containment cellar. The release was contained within the cellar.

Describe Area Affected and Cleanup Action Taken * There did not appear to be lateral migration of the spill. The spill was detected promptly and a vacuum truck immediately recovered the oil within the cellar walls. Quick response resulted in recovery of oil and approximately 10 yards of impacted soil was excavated and hauled to land farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Winn	Approved by District Supervisor:  For: Charlie Perrin	
Title: Environmental Coordinator	Approval Date 12-27-06	Expiration Date
E-mail Address: Lisa_Winn@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date 12/21/06 Phone: 505-566-7942		

* Attach Additional Sheets If Necessary

nBP0711033468