

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

APR 30-045-29426

**OPERATOR**

X Initial Report

☒ Final Report

Name of Company: Elm Ridge Exploration CO LLC	Contact: Amy Mackey
Address: PO BOX 156 Bloomfield, NM 87413	Telephone No. 505-632-3476 x 201
Facility Name: FARFELU #1	Facility Type: Gas Well

Surface Owner: Federal	Mineral Owner	Lease No.: SF-078063
------------------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter I	Section 19	Township 25N	Range 11W	Feet from the 1650'	North/South Line South	Feet from the 880'	East/West Line East	County San Juan
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	--------------------

**NATURE OF RELEASE**

Type of Release: Oil leak	Volume of Release: 5 bbls	Volume Recovered: 5 bbls
Source of Release: Tank bottom	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 2-16-06
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Monica Kuehling found the leak.	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD AUG 27 '07

OIL CONS. DIV.  
DIST. 3

If a Watercourse was Impacted, Describe Fully.*
---

Describe Cause of Problem and Remedial Action Taken.* The tank developed a corrosion leak at the bottom. We then emptied the tank and put a new tank on the location.
--

Describe Area Affected and Cleanup Action Taken.* The leak was with in the berm built around the tank. We vacuumed out the water/oil and put new dirt in the berm.
---

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy Mackey		Approved by District Supervisor: <i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Title: Production Technician		Approval Date: 8-27-07	Expiration Date:
E-mail Address: amackey1@elmridge.net	Conditions of Approval:		Attached <input type="checkbox"/>
Date:	Phone: 505-632-3476 x 201		

\* Attach Additional Sheets If Necessary

nBP 072604 8319