District I 1625 N. French Dr , Hobbs, NM 88240 District'II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr , Santa Fe, NM 87505

Date: 6/3/02

* Attach Additional Sheets If Necessary

Phone: 505-599-3454

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

	e Action	1	AME	NDE	D'REI	PQŘ T	•								
	30	2452	7466	2		OP.	ERATO	R	PSZ.	CX	iv. <i>Gly</i>] I nitial]	Report	Χ	Final Report	
Name of Company							Contact $\Box R$.	A. W	irtanen	>	٠, د/				
Phillips Petroleum Company							Telephone No. 505-599-3462 01 81 1								
Address 5525 Hwy. 64 Farmington, NM 87401							1 etephone 110. □ 303-377-3402-300								
Facility Name							Facility Type□ Gas Well								
San Juan 32-8 Unit #253							,								
Surface Owner Mineral Owner										·····	Lease N	o.□SF-	080412	<u> </u>	
							d Management								
LOCATION OF RELEASE															
Unit Letter	Section	Township	Range				South Line				t/West Line County [San Juan	
G	27	32N	8W	182	24'	N	orth	1	757'	<u> </u>	East				
NATURE OF RELEASE															
Type of Release							Volume of Release				Volume Recovered □ -0- recovered				
Produced Water Source of Release							Estimated 27 bbls Date and Hour of Occurrence				Date and Hour of Discovery□6/1/02				
Centrifugal pump seal failure on transfer pump							5/31/02 probably				AM by PPCo Operator				
Was Immediate Notice Given?							If YES, To Whom?								
X Yes No Not Required															
By Whom? Patsy Clugston – Sr. Regulatory Clerk							Date and Hour □ 6/3/02 @ 10:30 am								
Was a Watercourse Reached? Yes X No							If YES, Volume Impacting the Watercourse. N/A								
If a Watercourse was Impacted, Describe Fully.* A watercourse was not reached.															
Describe Cause of Problem and Remedial Action Taken.* The centrifugal pump (5 stage Reda Pump) had a seal failure & approximately 27 barrels of produced water leaked onto ground. The pump was															
not in a bermed area, but no water left location. The soil was so dry that the just soaked up the water.															
Describe Area Affected and Cleanup Action Taken.* Spilled produced water did not leave location. No further cleanup is anticipated. The water soaked into soil.															
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and														ules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger														ndanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health															
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other															
federal, state,	, or local la	ws and/or regi	ulations.			Т			TT GOLT						
Signature: Latsey Clust							OIL CONSERVATION DIVISION 1) Jenny Jeens								
Printed Name	A	Approved by District Supervisor: For Frank Chave 2													
Title: Sr. R	A	Approval Date: 6/07/0 > Expiration Date:													
Date: 6/3/02 Phone: 505 500 3454							Conditions of Approval:								

Conditions of Approval: