

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico

Energy Minerals and Natural Resources Department

Oil Conservation Division


2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to:
Appropriate District
Office in accordance
with Rule 116.



Release Notification and Corrective Action

30 045 30068

OPERATOR

☐ Initial Report

☒ Final Report

Name: Burlington Resources	Contact: GREGG WURTZ
Address: P.O. Box 4289 Farmington NM 87499	Telephone No.: (505) 320-2653
Facility Name: SUNRAY B 1C	Facility Type: Gas Well

Surface Owner: FED	Mineral Owner: FED	Lease Number: NMSF-078208
--------------------	--------------------	---------------------------

LOCATION OF RELEASE

Unit Letter: K	Section: 15	Township: 030N	Range: 010W	Feet From the: 1720	North/South Line: SOUTH	Feet From the: 1665	East/West Line: WEST	County: San Juan
----------------	-------------	----------------	-------------	---------------------	-------------------------	---------------------	----------------------	------------------

NATURE OF RELEASE

Type of Release: PRODUCED WATER	Volume of Release: 12 BBLS.	Volume Recovered: 3 BBLS.
Source of Release: Steel water drain tank	Date and Hour of Occurrence: 9/2/2002 8:00:00 AM	Date and Hour of Discovery: 9/3/2002 8:00:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If Yes, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0	

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

None impacted

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Hole in bottom of steel tank. Tank will be replaced with new tank and soils will be raked and turned to help break up salt crusting on soil and expedite natural remediation process.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Area within berm approximately 20 feet by 20 feet and approximately 1 foot deep.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gregg Wurtz</i>	OIL CONSERVATION DIVISION	
Printed Name: Gregg Wurtz	Approved by: <i>Denny Jent</i>	District Supervisor: <i>for Frank Chavez</i>
Title: Environmental Representative	Approval Date: 9/11/02	Expiration Date:
Date: 9-5-02 Phone: (505) 326-9841 or 326-9842	Conditions of Approval:	Attached: <input type="checkbox"/>

M DGF 0225436575