District I 1625 N French Dr, Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr, Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

APIH	30 -	045-31	0681			OPERAT	OR		Initial	Report		Final Report	
Name of Company XTO Energy Inc.						Contact Kim Champlin							
Address #382 County Road 3100 Aztec, NM 87410						Telephone No. (505) 333-3100							
Facility Name WF Federal 25 #1						Facility Type Gas Well							
Surface Owner Federal Mineral Owner						Lease No. NMNM02070010							
				LOCA	OIT	N OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/W	est Line	County			
Н	25	30N	14W	2130	Norti	h	575	East		San Juan	San Juan		
LatitudeLongitude													
NATURE OF RELEASE													
Type of Relea	ase Produ	ced Water		Volume of Release Approx 7 bbl Volume Recovered Approx 5 bbl						x 5 bbl			
Source of Release Pumping Tubing Line									Date and Hour of Discovery 12/30/07 at 9:30 am				
Was Immediate Notice Given?						If YES, To Whom?				RCVD JAN 11 'OB			
X Yes No Not Required						Brandon Powell- NMOCD				IL CONS. DIV.			
By Whom? Lisa Winn						Date and Hour 12/31/07 DIST. 3							
Was a Watercourse Reached? ☐ Yes ☐ No						If YES, Volume Impacting the Watercourse Approximately 2 barrels							
If a Watercourse was Impacted, Describe Fully *													
				lowing an incline	runnii	ng off location	and into a smal	Hunnam	ed dry wa	ish. An eme	ergency	v berm was	
									ica ary m	isin 7th Chi	or gene,	y berm was	
constructed within the wash to prevent further run off and samples were collected for analysis. Describe Cause of Problem and Remedial Action Taken *An XTO Lease Operator reported a release on location. Upon investigation it was													
	discovered the pumping tubing line from the wellhead to the separator had froze and split releasing approximately 7 barrels of produced water onto the ground. Approximately 2 barrels ran off location down an incline and into a small unnamed dry wash. The location was immediately shut in and a vac truck was dispatched. Approximately 5 barrels was recovered.												
		was dispatch and Cleanup A			reis wa	is recovered.							
				ontained by cons	tructir	ng a herm an <i>c</i>	vac truck was u	ised to re	ecover any	zstandino v	vater	Δn	
automation technician made repairs and the well was returned to production. Soil samples from the unnamed wash were collected for analysis. All notifications were made.													
													
				e is true and comp nd/or file certain re									
				ce of a C-141 repo									
				investigate and re									
or the enviror	nment In a	iddition, NMC	OCD accep	otance of a C-141									
federal, state, or local laws and/or regulations													
Signature: Kim Champlin						OIL CONSERVATION DIVISION							
Signature:	hm	(hau	n										
Printed Name. Kim Champlin						Approved by District Supervisor Branchon Panel For: Charlie Perrin							
Title: Environmental Representative						111.50			xpiration				
									1				
E-mail Address: Kim Champlin@xtoenergy.com						Conditions of Approval. Attached							
Date 1/10	0/08		Phone: 5	505-333-3100						1			

nBP0802951800