

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RCVD APR 23 '07
OIL CONS. DIV.
DIST. 3

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Lance Oil & Gas, Inc.	Contact Sharon Johnson
Address P. O. Box 70, Kirtland, NM 87417	Telephone No. (505) 598-5601 Ext. 15544
Facility Name Salty Dog #3	Facility Type Water Disposal Well
	API #30-045-31274

Surface Owner Bureau of Land Management	Mineral Owner Bureau of Land Management	Lease No. NM 97843
-----------------------------------------	-----------------------------------------	--------------------

LOCATION OF RELEASE

API # 30-045-31274

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	28	30N	14W	850	North	770	East	San Juan

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release ~150 bbls	Volume Recovered 0
Source of Release Water storage tank	Date and Hour of Occurrence 4-19-07 @ ~ 00:30 a.m.	Date and Hour of Discovery 4-19-07 @ 12:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD - Brandon Powell; BLM - Val Jamison and Mark Kelly	
By Whom? Sharon Johnson	Date and Hour 4-19-07 @ 2:00 p.m.	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. ~ 125 bbls	
If a Watercourse was Impacted, Describe Fully.* Water ran approximately 2000' and stopped. 2' wide to 2.5' wide, water soaked in to soil.		
Describe Cause of Problem and Remedial Action Taken.* Open valve on filter pot caused pump failure which allowed tank to over fill. Valve was shut and pump restarted.		
Describe Area Affected and Cleanup Action Taken.* Area around filter pot and down wash. When discovered, there was no free standing water to vacuum. Soil and tank water samples were taken. Affected area was flushed with 160 bbls fresh water and dragged.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>Sharon Johnson</u>		OIL CONSERVATION DIVISION	
Printed Name: Sharon Johnson		Approved by District Supervisor: <u>Brandon Powell</u> For: <u>Charlie Perrin</u>	
Title: Office Manager		Approval Date: <u>4-23-07</u>	Expiration Date:
E-mail Address: sharon.johnson2@anadarko.com		Conditions of Approval:	
Date: <u>4/20/07</u> Phone: (505) 598-5601 Ext. 15544		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nBP0719341725