

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Lance Oil & Gas, Inc.	Contact Sharon Johnson
Address P. O. Box 70, Kirtland, NM 87417	Telephone No. (505) 598-5601 Ext. 5544
Facility Name Salty Dog #4	Facility Type Salt Water Disposal Well
API #30-045-32334	

Surface Owner Bureau of Land Management	Mineral Owner Bureau of Land Management	Lease No. NMNM 101552
---	---	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	1	30N	14W	2580	South	1890	West	San Juan

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 320 bbls	Volume Recovered 320 bbls
Source of Release Tank battery	Date and Hour of Occurrence 2/4/07 during early morning hours	Date and Hour of Discovery 2/4/07 @ ~ 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Notice given 2/5/07: Sherrie Landon, BLM and Charlie Perrin, NMOCD	
By Whom? Sharon Johnson	Date and Hour 2/5/07 ~12:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	



If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.* Pump failure and line freeze resulted in spill. Pump was repaired, line freeze was thawed.

Describe Area Affected and Cleanup Action Taken.*

Spill was contained within berm. Water trucks removed water from berm. All water was put back in tanks.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Thomas M. Erwin		Approved by District Supervisor:  For: Charlie Perrin	
Title: Production Superintendent		Approval Date: 2-8-07	Expiration Date:
E-mail Address: tom.erwin@anadarko.com		Conditions of Approval:	
Date: 2/7/07 Phone: (505) 598-5601 Ext. 5563		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nBP0711037023

RCVD FEB8'07

OIL CONS. DIV.
DIST. 3