

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-33722

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	DECKER A	2F	Facility Type Gas Well
Surface Owner	Fee	Mineral Owner	Federal
		Lease No.	NMSF077648

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	03	031N	012W	1890	North	715	West	San Juan

NATURE OF RELEASE

Type of Release	Fresh Water with 2% KCL	Volume of Release	300 BBLS.	Volume Recovered	280 BBLS.
Source of Release	Frac Tank	Date and Hour of Occurrence	2/5/2007	Date and Hour of Discovery	2/5/2007 12:45:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Brandon Powell - OCD, Mark Kelly - BLM		
By Whom?	Ed Hasely	Date and Hour	2/5/2007 4:20:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.*
NA

RCVD FEB9'07
OIL CONS. DIV.
DIST. 3

Describe Cause of Problem and Remedial Action Taken.*



CHLUMBERGER MECHANIC TRUCK SLID INTO FRAC TANK #493 AFTER DRIVING BEHIND TANKS TO JUMP START THE SAND CHIEF. TRUCK BROKE OFF TANK VALVE AFTER COMING INTO CONTACT WITH TANK. RESULTED IN LOSS OF +/- 300 BBLS OF 2% KCL FRAC WATER. CREW MANAGED TO STAB A CONNECTION INTO TANK AND STOP FLOW. WATER WAS CONTAINED ON LOCATION, RAN INTO RESERVE PIT.

Describe Area Affected and Cleanup Action Taken.*

WATER WAS CONTAINED ON LOCATION. MOST OF THE RELEASED WATER RAN INTO RESERVE PIT.

API NO - 3004533722

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION	
Printed Name:	Ed Hasely			Approved by District Supervisor:	 For: Charlie Perrin
Title: Environmental Representative				Approval Date	2-9-07
E-mail Address: lhasely@br-inc.com or gwurtz@br-inc.com				Expiration Date:	
Date: 2/9/07	Phone: (505) 326-9841 or 9537			Conditions of Approval	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

nBP0711037350