

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Juanita Farrell
Address	5525 Hwy. 64, Farmington, NM 87401	Telephone No.	505-599-3419
Facility Name	Wood WN Federal Com 1M	Facility Type	Producing Gas Well
Surface Owner	Private	Mineral Owner	Federal
		Lease No.	SF-078266
			API # 30-045-30900

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	21	T29N	R10W	835'	North	1805'	East	San Juan

Latitude 36.71674° Longitude 107.89275°

NATURE OF RELEASE

Type of Release - Produced Water	Volume of Release - 31 BBL	Volume Recovered - none
Source of Release: Vandalism - Valve Opened	Date and Hour of Occurrence 3/22/05	Date and Hour of Discovery 3/22/05 - 2:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Denny Foust - OCD - via email Mark Kelly - BLM - via email	
By Whom? Juanita Farrell	Date and Hour - 3/22/05 - 4:20 p.m. via e-mail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully *		
Describe Cause of Problem and Remedial Action Taken.* A produced water spill of an estimated 31 BBL was discovered on 3/22/2005. Operations Supervisor, Tom Lentz discovered the spill during routine check of well site. Apparently vandals had opened valve to tank and allowed water to flow onto ground. Spill was contained in bermed area and there was no standing water to be recovered. Seal was replaced on valve.		
Describe Area Affected and Cleanup Action Taken.* Spill was contained in bermed area and there was no standing water to be recovered. This will be the final report.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Juanita Farrell</i>	OIL CONSERVATION DIVISION	
Printed Name: Juanita Farrell	Approved by District Supervisor: <i>Denny Foust</i> for <i>Charlie Penn</i>	
Title: Regulatory Analyst	Approval Date: 3/31/05	Expiration Date:
E-mail Address: Juanita.r.farrell@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/22/05	Phone: 505-599-3419	

\* Attach Additional Sheets If Necessary

n DGF 050905-3042