

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 039 24236

OPERATOR

x Initial Report Final Report

Name of Company: Devon Energy Production Co. L.P.	Contact: Steve Zink, Sr. Production Foreman	
Address: P.O Box 6459 Navajo Dam, N.M 87419	Telephone No.: 505 324- 5600	
Facility Name: Sims Mesa SWD	Facility Type: Salt Water Disposal Site	
Surface Owner: State of New Mexico	Mineral Owner: BLM	Lease No.: SF-79001

LOCATION OF RELEASE

Unit Letter E	Section 10	Township 30N	Range 07W	Feet from the 1450	North/South Line FNL	Feet from the 790'	East/West Line FWL	County Rio Arriba
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------------

NATURE OF RELEASE

Type of Release: Salt Water	Volume of Release: 160 bbl	Volume Recovered: 140 bbl
Source of Release: Valve left open	Date and Hour of Occurrence prior to 8.30 A.M 9-12-06	Date and Hour of Discovery: 9-12-06 8.30 Am
Was Immediate Notice Given? X Yes (within 24 hrs) <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Henry Villanueva	
By Whom? : Steve Zink (Devon Energy)	Date and Hour: 9-13-06 9.50 A.M	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*Had filters changed at SWD, contractors left drain valve open on secondary filter pots, we ran pumps a few days primary filters plugged off ,automatically switched to secondary filters. Action taken: Contractors will write up procedure for future filter replacement. Will go over procedures with Lease Operators. In addition, both Lease Operators and contractors will be at sight after filter change , both will double check sight.		
Describe Area Affected and Cleanup Action Taken.* Water was around pump houses and tanks inside dike. Had water truck suck up 140 bbl of water off of ground. Power washed inside pump houses, and gravel inside dike.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Steve Zink</i>	OIL CONSERVATION DIVISION	
Printed Name: Steve Zink	Approved by <input type="checkbox"/> District Supervisor: <i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Title: Sr. Production Foreman	Approval Date: 9/25/06	Expiration Date:
Date: 9/15/06 Phone: 505-320-0677	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

nBP0628430543