

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-039-24911

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Williams Production Co, LLC	Contact Michael K. (Myke) Lane
Address PO Box 640 / Aztec, NM 87410	Telephone No. (505) 634-4200
Facility Name Rosa Unit 271	Facility Type Well Site

Surface Owner BLM	Mineral Owner BLM	Lease No.
-------------------	-------------------	-----------

LOCATION OF RELEASE

Unit Letter G	Section 35	Township 31N	Range 05W	Feet from the 1810	North/South Line FNL	Feet from the 1850	East/West Line FEL	County Rio Arriba
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release ~50 BBL	Volume Recovered ~50BBL
Source of Release Frozen drain valve on storage tank	Date and Hour of Occurrence 12/16/07 Prior to 16:00	Date and Hour of Discovery 12/16/07 ~16:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Myke Lane	Date and Hour 01/03/08 08:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD JAN 3 '08

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV.

DIST. 3


Describe Cause of Problem and Remedial Action Taken.*

Drain valve to produced water tank frozen. While attempting to open valve damaged valve stem preventing valve from closing completely. Tank pulled. However, damaged valve allowed water to seep from tank. All water contained in containment. Due to frozen soil conditions essentially all water recovered by vac truck.

Describe Area Affected and Cleanup Action Taken.*

Upon discovery, well shut-in while tank valve replaced and heating element inspected to ensure tank heater properly operating during freezing conditions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Michael K. Lane		Approved by District Supervisor: Branch Powell For: Charlie Perrin	
Title: EH&S Specialist		Approval Date: 1-3-08	Expiration Date:
E-mail Address: myke.lane@williams.com		Conditions of Approval:	
Date: 1/3/08 Phone: 505-634-4219		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

n BPO800938491