

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RCVD NOV 14/06
OIL CON. DIV.
DIST. 3

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 23727

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Kevin Hansford
Address 200 Energy Court	Telephone No. (505) 326-9279
Facility Name State Gas Com A 1R	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	Lease No.
------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter H	Section 16	Township 29N	Range 09W	Feet from the 1530	North Line	Feet from the 830	East Line	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	------------	-----------------------------	-----------	---------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release: Condensate	Volume of Release 14 bbls.	Volume Recovered 0
Source of Release: Production Tank	Date and Hour of Occurrence: 8/3/06 Morning	Date and Hour of Discovery 8/3/06 12:30 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* During site inspection Triple S gauger noticed that the production tank was leaking. He immediately called for a truck to transfer the remaining fluids. The fluids were coming from the bottom of the tank.

Describe Area Affected and Cleanup Action Taken.* This well was shut-in, inspected, cleaned up and the tank was repaired. All fluids remained within secondary containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kevin Hansford	Approved by District Supervisor:  For: Charlie Perrin	
Title: Field Environmental Coordinator	Approval Date: 11/14/06	Expiration Date:
E-mail Address: hanske@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/09/06	Phone: 505-326-9279	

* Attach Additional Sheets If Necessary

uBP06 32553495