

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe. NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

APC 30-045-25349

OPERATOR ☐ Initial Report ☒ Final Report

Name of Company XTO Energy Inc.	Contact Kim Champlin
Address #382 County Road 3100 Aztec, NM 87410	Telephone No (505) 333-3207
Facility Name LC Kelly #1E	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	Lease No. NMSF 081239
------------------------------	---------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	5	30N	12W	930	North	1700	West	San Juan

Latitude 36.84615 Longitude 108.12417

NATURE OF RELEASE

Type of Release Condensate	Volume of Release Approx 7 bbl	Volume Recovered Approx 0 bbl
Source of Release Load Line	Date and Hour of Occurrence 11/13/07, time unknown	Date and Hour of Discovery 11/13/07 at 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse NA	

**RCVD NOV 30 '07
OIL CONS. DIV.**

If a Watercourse was Impacted, Describe Fully *
NA

DIST. 3

Describe Cause of Problem and Remedial Action Taken ***An XTO Lease Operator discovered the load line valve was cracked open and condensate was dripping onto the ground. The lease operator immediately closed the valve to stop the flow. Upon investigation it was discovered that the load seal had been broken in what appears to be an attempt at theft or vandalism. Approximately 7 barrels of condensate was missing from the tank and the ground around the tank was stained. The incident was reported to the Sheriffs department. A new dart and seal were placed on the load line and the ground was cleaned up.**

Describe Area Affected and Cleanup Action Taken ***The release remained on location. The valve was immediately closed to stop the flow of the release. All repairs to the equipment were made and the ground was cleaned up.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature <i>Kim Champlin</i>		OIL CONSERVATION DIVISION	
Printed Name Kim Champlin		Approved by District Supervisor <i>Frank Pelt</i> For: <i>Charlie Perrin</i>	
Title Environmental Representative		Approval Date 11/30/07	Expiration Date
E-mail Address Kim_Champlin@xtoenergy.com		Conditions of Approval	
Date 11/26/07	Phone 505-333-3207	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

~BP0734044294