

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30-045-27622

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	LEWIS PARK 101	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
Lease No.	NMNM-82815		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	13	031N	008W	975	South	870	West	San Juan

NATURE OF RELEASE

Type of Release	Produced Water w/ some oil	Volume of Release	95 BBLS	Volume Recovered	95 BBLS
Source of Release	Pit Tank	Date and Hour of Occurrence	8/8/2006	Date and Hour of Discovery	8/8/2006
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Brandon Powell		
By Whom?	Ed Hasely	Date and Hour	8/10/06 2 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken.\*

A valve was shut on the storage tank causing all water to be directed to the pit tank. The pit tank overflowed into the containment (cribbed area) around the pit tank. The spilled fluid was mainly Fruitland Coal produced water, but it did contain a small amount of compressor oil.

Describe Area Affected and Cleanup Action Taken.\*

All fluids were contained inside the cribbed area around the pit tank. The area also contained stormwater from before the spill event. A vacuum truck was used to recover the standing fluids. Due to the stormwater, we feel that we recovered all of the spilled fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Ed Hasely	Approved by District Supervisor:	For: Charlie Perrin
Title:	Environmental Representative	Approval Date	8/15/06
E-mail Address:	lhasely@br-inc. com or gwurtz@br-inc.com	Expiration Date:	
Date:	8/10/06	Conditions of Approval.	Attached
Phone:	(505) 326-9841 or 9537		<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

nBP0623426083