

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

API 30-045-28566

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Gregg Wurtz
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	
Facility Name	ALBINO CANYON	101	Facility Type Gas Well
Surface Owner	Mineral Owner	Lease No.	K-5808-NM

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	032N	008W					San Juan

NATURE OF RELEASE

Type of Release	Produce Coal water	Volume of Release	400 BBLs	Volume Recovered	375 BBLs.
Source of Release	Water storage tank	Date and Hour of Occurrence	3/20/2006 3:00:00 PM	Date and Hour of Discovery	3/20/2006 3:00:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
None



Describe Cause of Problem and Remedial Action Taken.\*

Storage Tank drain valve was left open by truck operator. The valve was closed and the water hauling company was contacted to remind operators to close valves. The truck operator was released from company. The standing water was recovered to the extent practical. A small area on location outside of berm contained standing water. All water was contained on location. Area will be raked to promote evaporation.

Describe Area Affected and Cleanup Action Taken.\*

Water was contained within berm for water storage tank except for a minor amount seeping outside the berm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION 		
Printed Name: Gregg Wurtz	Approved by District Supervisor: for Charlie Perron		
Title: Environmental Representative	Approval Date: 3/30/06	Expiration Date:	
E-mail Address lhasely@br-inc.com or gwurtz@br-inc.com	Conditions of Approval:	Attached	
Date: 3/23/06	Phone: (505) 326-9841 or 9537	<input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

NDG F0608940618

