

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API # 30-045-30089 OPERATOR ☐ Initial Report ☒ Final Report

Name of Company XTO Energy Inc.	Contact Lisa Winn	
Address 2700 Farmington Ave, Bldg K, Ste. 1, Farmington, NM 87401	Telephone No. (505) 566-7942	
Facility Name Chrisman Gas Com #2	Facility Type Gas Well (Fruitland Coal)	
Surface Owner Fee	Mineral Owner BLM	Lease No. NMNM-073918

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	11	30N	12W	20905'	South	1155	West	San Juan

Latitude 36.82528 Longitude 108.07206

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release Approx 12 bbl	Volume Recovered N/A
Source of Release load line valve on a water tank found half open	Date and Hour of Occurrence 02/16/06, time unknown	Date and Hour of Discovery 02/16/06 at 5:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken *☐ A call from Key Energy Service was received reporting water on the ground at this location. When XTO personnel arrived at the site, the load line valve on the water tank was found half open and the plug lying on the ground. The valve was shut and a roustabout crew was dispatched for clean up. Remedial Action: Soil was turned and dragged with a backhoe.

Describe Area Affected and Cleanup Action Taken *☐ The water was on the well pad and approximately 200 feet along the lease road leading into the well pad. A backhoe dragged the road and affected area. A lock was placed on the load valve.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Lisa Winn	OIL CONSERVATION DIVISION	
Printed Name: Lisa Winn	Approved by District Supervisor: Jerry Zait for Charlie Perrin	
Title: Environmental Specialist	Approval Date: 3/13/06	Expiration Date:
E-mail Address: Lisa_Winn@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02/20/06 Phone: 505-566-7942		

* Attach Additional Sheets If Necessary

NDGF 060724 2185

