

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

API 30-045-31199

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy	Contact	Steve Zink
Address	P.O. Box 6459 Navajo Dam NM 87419	Telephone No.	505-324-5605
Facility Name	NEBU 50A	Facility Type	Production Well Location

Surface Owner	Devon Energy	Mineral Owner	BLM	Lease No.	SF 79082
---------------	--------------	---------------	-----	-----------	----------


### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	25	31N	8W	760	North	1860	West	San Juan

Latitude 36 deg. 52' 26" N Longitude 107 deg. 37' 47" W

### NATURE OF RELEASE

Type of Release	BJ Chemical Techni-Hib 7371 Scale Inhibitor	Volume of Release	60 gallons	Volume Recovered	0
Source of Release	Storage barrel tipped over	Date and Hour of Occurrence	5/16/06 10:00 am	Date and Hour of Discovery	5/16/06 10:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Steve Zink	Date and Hour	5/17/06 8:45 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

While attempting to move the barrel, it tipped over and knocked open the top lid. The lid was replaced, stopping the spill. A dike was constructed around the affected area.

Describe Area Affected and Cleanup Action Taken.\*

Affected area is on the north side of the wellhead. Size of affected area is approximately 6' x 10'. Envirotech has been called in to removed the contaminated soil and replace it with clean soil. This will be done on Friday, May 19<sup>th</sup>.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Steve Zink</i>		
Printed Name:	Steve Zink		
Title:	Sr. Production Foreman		
E-mail Address:	Steve.Zink@dm.com		
Date:	5/18/06	Phone:	505-320-0677
		OIL CONSERVATION DIVISION	
		Approved by District Supervisor: <i>Brandon Powell</i> For <i>Charlie Perrin</i>	
		Approval Date:	05/22/2006
		Expiration Date:	
		Conditions of Approval:	
		Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

n 890614341116